




2019 BIENNIAL STRUCTURE INSPECTION PROGRAM

Township of South Stormont – September 2019



Keystone Bridge Management Corp.

Your Bridge Asset Management Specialist

Contents

Executive Summary.....	1
Introduction	2
Structure Summary Statistics.....	3
Bridge and Culvert Lists.....	3
Capital Needs Report	3
Bridge Maintenance.....	4
Estimated Remaining Service Life and Replacement Costs	5
Estimated Remaining Service Life	5
Replacement Cost	5
Summary Results.....	6
Caveat	6
Culvert Replacement Cost Report.....	6
Bridge Replacement Costs	7
Bridge Depreciation	7
Bridge Depreciation Forecast.....	9
Bridge Depreciation Forecast with Recommended Capital Investment.....	9
Average Bridge Depreciation with Investment Report.....	10
Culvert Depreciation Forecast	11
Average Culvert Depreciation with Investment.....	11
Recommended Investigations Report.....	12
Performance Deficiencies	12
Bridge Condition Index.....	12
Traffic Barriers.....	13
Bridge Image Report	13
Triple-D Inspections	13
Understanding the Inspection Forms	14
Tombstone Data.....	14
Inspection Summary Data.....	15
Vital Statistics.....	15
Bridge Condition	15



Component Inspection Information	15
Defects	16
Damage.....	16
Maintenance	16
Capital Recommendation.....	16
Remark	16
Performance	16
Capital Needs Cost Estimate Breakdown.....	16
Inspection Images	17
Digital Copy	17
Limitations	18
Decision Support.....	18
Other Caveats	18
Closing.....	19



Executive Summary

Keystone Bridge Management Corp. was retained by the Township of South Stormont to provide bridge assessments for all its bridges and large culverts. A total of 22 structures were evaluated of which 9 were bridges and 13 were culverts.

The structure inventory ranges in age from nearly new to 69 years old and represents 1,861 square metres of plan surface area. The average age of South Stormont structures is 31 years.

The asset value of all bridges and culverts on a full replacement cost basis is of the order of \$11.2 million.

Approximately \$2.4 million is required in capital investment to continue to maintain the structural inventory in good serviceable condition for the next six years. Four culverts are identified for replacement. Two bridges are nominated for a comprehensive rehabilitation.

In the next 20 years there will be a need to replace about \$3M in bridge and culvert assets.

The bridges are presently depreciating at a rate of \$110K per year. They retain about 67% of their new value. In the absence of capital investment, the bridges will retain 36% of their new value in 20 years. The bridges have lost 7.3% in value due to deterioration. The ideal long-term investment in bridges is \$100K annually.

The culvert assets are depreciating at a rate of \$50K per year. They currently retain about 43% of their new value. Without capital investment, the culverts will retain 15% of their new value in 20 years. The recommended on-going expenditure for culverts is greater than \$60K annually.

A total of 59.1% of the inspected structures have a Bridge Condition Index greater than 70. The remaining structures have BCI values between 57.1 and 70. South Stormont is 20.9% behind the MTO's goal of maintaining at least 80% of its structures with a BCI greater than or equal to 70.



Introduction

This is the first biennial cycle of bridge and large culvert assessments by Keystone Bridge Management (KBM) on behalf of the Township of South Stormont. Since 2006 KBM has continuously improved and developed new features and reports that better characterize the condition of bridge and large culvert inventories. It is now our pleasure to present these improved reports on the present condition and outlook of the Township of South Stormont bridge and large culvert assets.

Biennial inspection of bridges and culverts with a span equal to or exceeding 3.0 metres is mandated by provincial statute in Ontario. Municipalities seeking provincial funding for structure capital improvements are required to demonstrate their bridges receive a biennial inspection. Increasingly, the government is expecting municipalities to have an asset management plan as well.

All the structures were inspected over four days in the period between July 5th and August 21st, 2019. Water levels and weather conditions were mostly ideal for the inspection field work. However, high water levels in the St. Lawrence River limited the substructure view of the Shaver Bridge.

Provided herein are detailed capital needs, maintenance needs, individual bridge depreciations to date, forecast inventory depreciation, and the bridge condition index, for all the inspected structures. The estimated remaining service life and replacement cost is detailed for each structure. The individual inspection reports (134 pages) are bound with this Report.

The following network level reports are appended to this Summary Report and are further described and explained herein:

1. Statistical Report
2. Bridge List
3. Culvert List
4. Capital Needs
5. Maintenance List
6. Structure Replacement Cost & Estimated Remaining Service Life Report
7. Culvert Replacement Cost Report
8. Bridge Parabolic & Straight-Line Depreciation
9. Bridge Depreciation Forecast
10. Bridge Depreciation Forecast with Recommended Capital Investment
11. Bridge Average Depreciation with Investment Scenarios
12. Depreciation Forecast – Culverts
13. Average Culvert Depreciation with Investment Scenarios
14. Recommended Investigations
15. Performance Deficiencies
16. BCI Report
17. Bridge Images Report (On digital medium only)



Structure Summary Statistics

A snapshot one-page **Structure Summary Statistics Report** immediately follows this Summary Report. The Structure Age Histogram shows that the South Stormont structures have a reasonably even age distribution. Six structures are new or have been replaced in the past 20 years. The average age of South Stormont structures is 31.0 years. There is one structure that is more than 60 years old. It is 69 years old.

The Structure Deck Area Histogram demonstrates that most of the structures have less than 100 square metres of plan area. The largest structure has a plan area of 207 square metres. The average plan area is 85 square metres. The total plan area of structural assets is 1,861 square metres. Bridges with more than 600 square metres of deck surface are considered large bridges. South Stormont has no large bridges.

The Structure Deck Area per Age Histogram is a hybrid of the previous two histograms. It is a key piece of asset management information because this chart presents the age and size-weighted picture of the structure inventory. The plot shows a variable unbalanced distribution. About 6.3% of the deck area is greater than 50 years old. About 34.1% of the deck area has been renewed in the past 20 years. This is a renewal rate of 1.7% per year. A rate of at least 1% per year renewal is critical for a sustainable inventory. Fortunately, South Stormont has been able to exceed the minimum renewal rate.

Bridge and Culvert Lists

A printout of the client's bridges and culverts is provided. This printout clarifies what are considered as bridges and which structures are deemed culverts. Culverts are defined as an opening through the embankment, and by definition, have soil cover.

Bridges typically have no cover, although certain bridges may have had their riding surface elevated by infilling between the curbs. The Bridge List identifies nine structures that are considered bridges by the Township of South Stormont. The remaining 13 structures on the inventory are culverts

The bridge management analysis differentiates between bridges and culverts and this is further explained later in this Summary Report.

Capital Needs Report

The capital needs were estimated with an estimating tool contained in the Keystone Bridge Management System. This utility covers common items that include deck replacement, expansion joint replacement, barrier wall replacement, waterproofing and paving. The utility provides guidance for traffic management costs. All costs are marked up 20% to account for contingencies and engineering. Contract administration costs are not included.

Where capital needs call for structure replacement, the replacement cost of the existing structure is considered. Typically, the capital cost for replacement exceeds the replacement-in-kind cost, especially for bridges with functional deficiencies such as inadequate road platform or that impede conveyance of the channel they are crossing. Keystone almost always recommends concrete culverts to replace corrugated steel ones, and this is reflected in the capital estimates.



The Capital Needs for The Township of South Stormont are summarized in a separate report, included in the Network Reports section of this Report.

The **Capital Needs Report** is organized from the most immediate needs to the less immediate needs by the Recommended Year sub-headings. Two capital needs pictures are graphically presented at the end of the Report. A Grand Total of **\$2,411,000** is the projected capital need from the present to 2024.

There are 14 Capital Projects identified over the six-year planning period to 2024. Four culverts are recommended for replacement. Two bridges are scheduled for a comprehensive rehabilitation.

The distribution of capital needs is depicted in two different graphs at the end of the Capital Needs Report. The first graph shows the inventory needs and a line of “best fit” that describes the average needs over the planning period. The average six-year outlook is about \$400K in capital per year.

The second graph breaks down the capital expenditures between bridges and culverts. Culvert needs predominate over bridge needs.

The capital needs groupings in the Capital Needs Report suggests relative priority, but other considerations such as traffic demand, risk of failure, and combining projects should also be considered to establish actual priorities.

Please note the capital estimates provided are very approximate by nature. Environmental considerations, difficult foundations, dewatering requirements, and traffic management costs can be very significant variables that can only be estimated accurately at the preliminary design stage. Culvert replacement cost estimates are premised on replacement with a similar sized culvert, but typically concrete culverts are chosen over steel.

Bridge Maintenance

Detailed maintenance needs are captured in the **Bridge Maintenance Report** in the Network Reports section of this Report.

Maintenance needs shown in **red font** are considered the most urgent.

Some of the more common maintenance needs identified are:

- Removal of brush and trees
- Removal of obstructions in stream channels

The Township of South Stormont is providing appropriate maintenance to most of the structures inspected.

The maintenance list is provided to guide additional maintenance work that will help maintain the life and serviceability of the structures, and in some instances, improve safety. These maintenance items are duplicated in the individual structure reports.

Bridge cleaning is widely recognized as an important maintenance activity. Ideally spring maintenance should include a thorough sweeping of the bridges' horizontal surfaces, and power washing of the bridge seats especially where expansion joints are open, or the seal is



compromised. Early sweeping removes brine laden winter sand from the bridge decks. This greatly helps forestall the onset of corrosion of the reinforcing steel. Expansion joints should be cleaned of debris caught inside the gaps in the spring and fall of each year.

Removal of obstructions in stream channels is mentioned in the Maintenance Report. Brushing out improves air circulation around structures and this is an important maintenance activity. South Stormont should be more proactive controlling brush around its structures.

A common rule of thumb is to spend 1% of the replacement value per annum on structure maintenance. In practise, few municipalities spend even 0.1% of replacement value on bridge and large culvert maintenance. The most responsible division of capital and maintenance expenditures is elusive. Suffice to say that a productive and skilled maintenance crew can achieve significant reductions in capital needs while maximising the serviceability and service life of those structures they maintain.

Estimated Remaining Service Life and Replacement Costs

The estimated remaining service life (ERSL) and the replacement cost are vital asset management intelligence. These values are provided in a network level report.

Estimated Remaining Service Life

The structures are ordered based on the ERSL. The newest structures top the list. The structures at the bottom of the list, have effectively no or very little remaining service life. Those structures that have a formally identified capital need have the recommended program year identified. All structures with less than ten years of estimated remaining service life are identified on the capital program.

The ERSL is calculated based on the deemed life of the structure, and present age. This is modified by an algorithm that recognizes the actual condition of the structure. Old bridges in very good condition automatically have their lives extended. Newer structures in exceptionally poor condition have their life expectancy reduced. Recently rehabilitated bridges have their lives extended by not less than ten years. Thereafter, engineering judgement is applied to arrive at the listed ERSL.

Replacement Cost

The replacement costs are premised on replacement in kind. Typically, when a bridge is replaced, it is replaced with an improved structure type, and often to improved design criteria. Hence the replacement costs are not a reliable indicator of actual replacement costs. However, it is a very useful parameter for asset management purposes, particularly when assessing the level of asset depreciation.

The replacement cost considers numerous factors and is computed by an algorithm. The factors are listed below:

- Structure type
- Plan area of bridge (Overall length by overall width)
- Skew (cost increased by 10% if skew angle > 0)
- Symmetry (cost increased by 10% if irregular or unsymmetrical)
- Size (a discount factor is applied as the size increases)



- Aspect ratio (A very wide bridge has a lower unit cost)
- Allowance for existing structure removal

The base replacement cost is factored by an allowance for design costs and contingencies.

The culvert replacement costs are calculated separately, and this is explained later in this report.

Summary Results

The end of the report summarizes the remaining service life and replacement cost data. The estimated total replacement cost for the Township of South Stormont bridges and culverts is \$11,018,000. The average replacement cost per structure is nominally \$500K.

A graph forecasts the future costs for structure replacement by decade. In the next 20 years, there is a forecast requirement to replace almost \$3M in structure assets. The Township needs to strategize on how best to prepare for this significant road structure renewal cost.

Caveat

The estimated remaining service life is a guideline only. Rehabilitation can extend the life of a structure by 20 to 50 years. In some instances, the ERSL may be optimistic, especially for steel culverts.

The estimated replacement costs are a reasonable indication of actual replacement in-kind costs. However, there are numerous other considerations that influence replacement costs. Chief among these are market conditions, challenging foundation conditions, and traffic management requirements.

We welcome our clients actual cost experiences for structure replacements. This helps us better calibrate our estimating models.

Culvert Replacement Cost Report

The Culvert Replacement Cost Report is generated based on a complex algorithm within KBMS that considers parameters such as depth of cover, skew, water depth, road width, and presence of guide rail. The estimated replacement cost is generated for both a corrugated steel and concrete box type culvert.

Concrete culverts lag steel culverts by 2 to 11. Keystone's experience indicates that only shallow cover smaller diameter steel culverts in shallow water can be justified over concrete culverts on a life-cycle cost basis. The estimated life-cycle costs for both steel and concrete culverts is provided. The more favourable life-cycle cost is highlighted in green. In only three instances does a steel culvert have a slight life-cycle cost advantage over its concrete counterpart.

The estimated cost to replace all the Township of South Stormont culverts, in kind,¹ is \$3,523,000.

¹ Similar material and functionality



Bridge Replacement Costs

From the previous two network level reports it is easily deduced that the replacement value of only the bridges is \$7,495,000.

Bridge Depreciation

Included in the Network Reports section of this Report is the **Parabolic & Straight-Line Depreciation Report** for all the bridges. The large culverts are not included in this report.

The New Value of each bridge is premised on the geometry and deemed unit price of the main components and summing the individual values. The costs of foundations are not included. Foundations are very expensive bridge components that may cost from \$100K to \$1,000K per bridge foundation unit. The deemed unit prices are relative, and not necessarily reflective of current actual costs. Dollar values are current as opposed to historical values used in accounting practise.

Depreciation is premised on the actual age of each bridge component. So, for example if a bridge has replacement components such as expansion joints or new barrier walls, the depreciation of these components is based on their year of installation rather than the age of the original bridge. In some instances, judgement was required to establish the installation date of replacement and original bridge components.




Figure 1. Examples of four depreciation functions for a bridge component with an 80-year deemed service life.



The loss in relative value of a bridge due to Defects and Damage is shown as a percentage, and actual cost. For example, at the top of the first page of the report the North Lunenburg Bridge has lost 3.7% of its deemed New Value due to Defects and Damage assessed at the time of inspection. One percent damage devalues a component by five percent. Therefore, a component that is 20% damaged has lost all its value. Ten percent defects to a component is equivalent to one percent damage.

The Present Value (book value) of a bridge is expressed in terms of how much of the original value is retained after considering Depreciation, Defects and Damage. Depreciation is calculated as Parabolic or Straight-Line (S/L). With a parabolic depreciation function, only 25% of the depreciation takes place in the first half of the component's life. Parabolic depreciation sustains a bridge's value in the early part of its life. Straight-line depreciation is probably a more realistic and conservative approach to describing the current book value of a bridge. Examples of four depreciation functions are illustrated in Figure 1. on the previous page.

The previously cited bridge (31-170) was constructed in 2008. The deemed New Value of the bridge is shown as \$540,306. If parabolic depreciation is assumed, the bridge still retains 92.9% of its original deemed value. The Straight-Line depreciated value of the bridge is 79.5% of the new value.

The most telling part of this report is the bottom line. The deemed new value of all the bridge components is approximately \$4.4M. The loss in value to the assets due to Defects and Damage is assessed as 7.3% or \$320K. The total depreciated value of the bridge inventory is 73.0% of the deemed New Value if parabolic depreciation is assumed. Similarly, for straight-line depreciation the value has declined to 56.8% of the original deemed New Value.

Where the depreciation has reduced the value of a bridge by more than half, it is highlighted in amber in the report.

Assuming a 100 year write down period for bridges, it is a desirable goal to maintain the entire bridge inventory at nominally 50% depreciation or better if Straight Line Depreciation is adopted. Similarly, for Parabolic Depreciation, it is desirable to maintain the level of depreciation at or above 67%.

Depending on the choice of Depreciation function, The Township of South Stormont is ahead of target by 6.8% or 6.0% respectively. These numbers are much better than most rural municipalities in Ontario.

When the depreciation due to defects and damage exceeds 25% the number is highlighted in yellow. There are no bridges where defects and damage account for more than 25% of the depreciation.

There is a significant disparity between the estimated full replacement value of the bridge assets (\$8.7M explained earlier in this report) and the value generated in the Parabolic & Straight-Line Depreciation Report. The principal reason for this is because the cost of the bridge foundations is not included in the depreciation calculations, and the deemed unit values of components is possibly too low. Also, the estimated replacement costs consider traffic management, design and contingency costs, whereas the deemed new values in the Depreciation Report do not.



Continued and somewhat greater strategic investment in rehabilitation and renewal will improve the depreciation numbers. Those structures with more than 10% Damage/Defects should be prioritized for rehabilitation.

Bridge Depreciation Forecast

In the Network Reports Section of this report is a forward-looking graphical representation of the projected depreciation of the inspected bridge components. The aggregate value of the inspected components is shown in terms of the Original Value as 100 percent, the Present Depreciated percentage level (Now), and the Forecast Depreciated percentage level in five-year increments extending 20 years hence.

The Depreciated percentage is calculated based on the deemed value, deemed life, and age of each bridge component. Once Defects or Damage is identified on a component, the Defects and/or Damage is assumed to grow at 0.5% per year non-compounded. Thus, a sidewalk that presently has 5% scaling (a Defect), is assumed to have 7.5% scaling in another five years time.

Examining the mauve bars in the graph, the Original Value expressed as 100% has declined to 78% retained value considering only parabolic depreciation. A further 27 percentage points of depreciation is forecast over the following 20 years.

Contrast this against the scenario of straight-line depreciation including on-going growth of defects and damage. This is represented by the light green bars in the graph. The Original percentage declines to 56% retained value with a further 33 percentage points decline in the next 20 years.

The projected average depreciation is 1.5 percent per year. Accepting an actual replacement cost of \$7.5M for only the bridge assets, the forecast depreciation loss in terms of replacement value is nominally \$110K per year. Hence an annual capital expenditure of not less than this amount is required just to maintain the bridge inventory at present levels of depreciation.

Bridge Depreciation Forecast with Recommended Capital Investment

Immediately following the **Depreciation Forecast** in the Network Reports, is a similar looking chart as the Depreciation Forecast. However, this second chart demonstrates the effects of investing the recommended Capital Needs into the bridge inventory. It is very clear that investing the recommended Capital expenditures helps increase the value of the bridges, and improves the depreciation outlook.

It is very important to understand this chart speaks only to bridges. The culverts are discussed separately in the sections following.

The premise for this chart is as follows. The recommended capital investments from the Capital Needs Report are grouped in five-year groupings. Hence all the recommended capital needs for bridges from the present to five years out is grouped, and so on and so on for 6 to 10-year needs, 11 to 15-year needs, and 16 to 20-year needs. The Capital is deemed to be spent exactly as recommended. The recapitalization of the bridge inventory offsets the depreciation.



The graph shows that the recommended capital spending for the first five years improves the depreciation. Thereafter the spending is insufficient to keep up with depreciation.


The deemed depreciated value is factored by the Estimated Replacement Value for all the bridges. Hence the recapitalization is applied against the Estimated Total Replacement Value rather than the deemed values utilized for calculating relative depreciation.

One further premise requires explanation. The graph is premised on one dollar of capital investment off sets one dollar of depreciation. This is reasonable when the replacement values of bridges include all the associated sundry costs of a bridge replacement in kind. Realistically, one dollar of capital may only offset eighty cents of depreciation.

In summary, this **Bridge Depreciation Forecast with Recommended Capital Investment** demonstrates that the recommended expenditures in the Capital Needs Report will, if followed exactly, greatly improve the level of depreciation in the first ten years, and thereafter depreciation will outpace capital renewal.

Average Bridge Depreciation with Investment Report

In the Network Reports Section immediately following the previous chart is a related chart that tests various investment strategies and their impact on long term depreciation. This chart is named the **Average Bridge Depreciation with Investment Report**. An example is depicted on the following page.



As the title suggests, this chart considers the Average Depreciation. In the previous two charts, four different types of depreciation assumptions are provided. In this chart, the four assumptions are averaged. The resulting average is shown as a red line captioned as “Invest 0”. For the Township of South Stormont, the average level of depreciation is about 67% of New Value and is projected to decline to 36% of New Value in 20 years in the absence of capital investment.

Superimposed on the Zero Investment scenario are four other colour coded investment scenarios

labelled **Invest 1** to **Invest 4**. The **Invest 1** scenario models the effect of following the Capital Needs Report exactly as recommended. The average investment is \$44K per year for 20 years.

Examining the chart, and in particular, the green line that represents this investment scenario, it is shown that the recommended capital expenditure will improve the retained value to 69% in 5 years. Thereafter the retained value declines to 45% of new value in the following 15 years.

The three other investment scenarios correspond to investing 0.75%, 1.0%, and 1.5% of the replacement cost of the bridge inventory annually. It is evident that only a long-term investment of at least 1.0% to 1.5% of the replacement value annually will maintain the bridge assets at desirable depreciation levels. The Township of South Stormont should commit to spending not less than \$100K per year on their bridges for the foreseeable future.



Culvert Depreciation Forecast

A chart showing forecast **Culvert Depreciation** is provided in the Network Reports. Culverts are treated very differently than bridges and this is explained next.

The new or Original Value of culverts is based on their replacement value. The replacement value of a culvert calculation was explained earlier in this report. Basically, the replacement value considers the costs of excavating the road surface, providing water control, removal of the existing culvert, and replacement in kind of the existing culvert. The costs include backfill and restoring the pavement structure of paved roads. The estimated cost to replace in kind the entire South Stormont culvert inventory is \$3,523,000. This works out to \$270,000 per culvert.

Straight-line depreciation is utilized to depreciate the culverts. Since the culvert conduit is only part of the cost of the entire replacement cost, it was deemed that only simple depreciation without considering the effects of defects and damage was the more appropriate depreciation model. Depreciation is based on the assumption of a 100-year life for concrete culverts and a 35-year life for corrugated steel and timber culverts. The assumed life is adjusted in the calculations to the estimated remaining service life.

The culverts are individually depreciated based on their age, condition and construction. The chart shows that the retained value of the culverts is about 43% of their Original or new value. In the absence of capital investment, the culverts will depreciate a further 28% in 20 years, or 1.4% per year.

Since the entire cost of culvert replacement is considered, then like the bridges, a dollar invested in culvert replacement yields a dollar improvement in the depreciated values. The depreciated value changes from \$1.52M to \$528K in 20 years. This is nominally \$50K per year. Thus, a minimum annual capital expenditure of \$50K per year is required just to maintain the present depreciated value of the culverts.

Previously it was noted the average cost of a culvert in South Stormont is \$270K. At a \$50K annual rate of depreciation, not less than one culvert on average should be programmed for replacement every five years, to maintain the current retained value. In actuality, a more aggressive replacement rate is required to address immediate needs.

Average Culvert Depreciation with Investment

A second chart that examines five different investment scenarios for culverts is also provided. Based on the Capital Needs Report, it was identified that about \$1.54M is required for culvert needs between the present and 2026.

The first, or null investment scenario shows that the depreciated value of the culverts will decline from 43% retained value to 15% retained value over 20 years.

The **Invest 1** scenario models the impact of capital investment following exactly the Capital Needs Report recommendations for culverts. This average level of expenditure of \$77K per year for 20 years results in the retained value of the culverts improving to 76% in five years, and thereafter declining to 59% after 20 years.

The **Invest 2**, **Invest 3** and **Invest 4** scenarios correspond to spending 0.75%, 1.0%, and 1.5% of the replacement value of the culverts annually. The chart confirms that a long-term annual



average expenditure of approximately \$60K per year (1.5% of replacement value) is required for culvert renewal in South Stormont Township.

Recommended Investigations Report

Biennial inspection of bridges as mandated by OSIM (Ontario Structure Inspection Manual) provides a cost-effective means of inspecting and reporting on the general condition of a bridge. Where, in the opinion of the Engineer, additional investigation is required, it is prescribed as part of the Inspection Report.

The one-page **Recommended Investigations Report** included with the Network Reports indicates that there are no recommended special investigations.

Performance Deficiencies

The various components in and around a structure all have a purpose or functionality. Where the purpose or functionality is compromised, it is recorded as a performance deficiency. Included in the Network Reports is a two-page **Performance Deficiencies Report**.

These deficiencies are often difficult or expensive to remedy. Ideally, a replacement structure should address the present performance deficiencies. These deficiencies should be reviewed when prioritizing the capital program. Bridges and culverts with numerous performance deficiencies, such as the Shaver Bridge should be prioritized for rehabilitation or replacement.

The more common performance deficiencies in South Stormont relate to guide rail and delineators.

Performance Deficiencies require risk management strategizing by the owner.

Bridge Condition Index

The calculation of BCI requires inspection following the OSIM Excellent-Good-Fair-Poor (EGFP) rating system. Up to 55 structural elements are considered in the calculation.

Keystone follows its proprietary Triple-D approach instead of the EGFP method of rating a bridge. To translate the Triple-D method to EGFP the following approach is observed. Anything considered Damaged in Triple-D format is mapped 1:1 as Poor in EGFP format. All bridge components transition from Excellent to Good in a straight-line decay function over a 20-year period. Thus, a new component becomes 10% Excellent and 90% Good after ten years of service. The determination of Fair is based on the percent Defects and considers the percent Damage loosely following OSIM philosophy and is performed following an algorithm implicit to KBMS. The percent Good is determined as 100% less the percent Excellent, Fair, and Poor. Excellent, Good, Fair, and Poor are weighted 1.00, 0.75, 0.40, and 0.0 respectively in the BCI calculations following the published MTO methods of July 2009.

The calculated BCI information is provided in the included report of the same name. Where the BCI is between 60 and 70 the index is printed in green font. Where the BCI is between 50 and 60 it is shown in orange font. Below 50 the BCI is shown in red font

Nine of the 22 inspected structures, or 40.9% have a BCI less than 70. Conversely, 59.1% of the structures have a BCI exceeding 70. The MTO's goal is to maintain at least 80% of its



structures with a BCI greater than or equal to 70. On this account, the Township of South Stormont is 20.9% behind this metric.

The lowest BCI of 57.1 is for Beckstead Road Culvert. Extensive heavy corrosion is mainly responsible for the low BCI value.

In summary, the BCI is a useful measure of the overall condition of common bridges and culverts but is still highly variable and dependent on the judgement of the individual bridge inspector. The BCI calculations could easily be ten points less if determined by others essentially because of the ambiguity and lack of consistency in differentiating between Fair and Poor in strict OSIM methodology inspections.

Traffic Barriers

Many consultants point out that traffic barrier systems such as railings on bridges and guiderail on embankments do not conform to current codes. Keystone avoids doing this.

The reasoning for this goes as follows. MTO has always recognized that a railing system constructed to the relevant standards of that time can remain in service for as long as that system is maintained in good serviceable condition, up until a major rehabilitation. Hence Keystone refrains from identifying traffic barriers that may not conform to the present standards or codes. It is still the responsibility of the owner to maintain the barriers in good serviceable condition.

Where a traffic barrier is substantially deteriorated to the point where maintenance repair is no longer a reasonable option, then Keystone recommends replacement. Such replacement would of course be designed and constructed to the latest standards.

There are many situations where structures (mostly culverts) are not protected by barriers. Keystone has recommended a review of the guiderail warrants for those situations where the client may have excessive liability by maintaining the status quo.

Bridge Image Report

A Bridge Image Report is provided with the digital data but not included with the printed reports. This seven-page report catalogues all the photos by structure ID, date, image number and caption. In some instances, the photo caption is truncated on the inspection reports. The full caption is available on the Bridge Image Report.

All the images are available in slightly compressed format in individual folders for each structure with the digital data provided as part of the assignment. We will retain the original images for not less than two years and they can be provided upon request.

Triple-D Inspections

The individual bridge inspection reports are bound separately from this Summary Report. The reports are a slight departure from OSIM Reports in that the field inspection effort is directed at identifying deterioration and performance issues as explained below.

Keystone's approach to Bridge Management is fundamentally different from all others anywhere in the world. Keystone models bridge assets in terms of their **D**epreciation, **D**efects, and



Damage. This “**Triple-D**” approach is unique to Keystone and is the soundest and most reliable method ever conceived to accurately ascertain or predict the condition of a bridge.

The “**Triple-D**” approach is imbedded in a highly sophisticated MS Access database application developed by Keystone. The design of the database easily facilitates porting the data to any other application and is highly customizable to any client.

Every bridge is modeled in terms of its components. Each component has a life expectancy and value based on its material and geometric properties. As a bridge ages, the components depreciate in accordance with a simple depreciation function that is client specified. Either a straight-line or parabolic depreciation function is recommended. The overall depreciation of a structure is expressed in terms of the sum of the depreciation of all the components.

This deterministic approach to assessing the condition of a bridge provides an extremely reliable, reproducible and predictable approach to stating the condition of not only a bridge, but an entire bridge inventory.

The concept of **Defects** and **Damage** is very easily understood and applied as compared to the more traditional subjective ratings of Excellent, Good, Fair or Poor. Consequently, the information resulting from bridge inspections is an order of magnitude more reliable and accurate.

Understanding the Inspection Forms

Inspection reports are headed **Bridge Inspection Report or Culvert Inspection Report**. In the top-right of each form is a general arrangement photograph of the structure taken on the day of inspection.

Tombstone Data

In the top-left box is basic tombstone data as follows:

- Name of the bridge in large bold font
- The road the structure is on
- The Owner identification alpha-numeric (Site ID)
- The type of bridge or culvert
- Name of the Owner
- Year of original construction per legacy information or our estimate.
- Length of the Bridge per legacy information or our measurement
- Width of the Structure per legacy information or our measurement
- Number of spans
- The span arrangement is shown in metres for bridges only.
- The main significant feature under the bridge
- The main feature the structure is crossing
- The name of the feature the structure is crossing
- Structure Location information



Inspection Summary Data

In the next box down is recorded the date of inspection, principal inspector, assistant inspector, the weather for the entire day, and the approximate temperature range on the day of inspection.

This is followed by summary comments for the structure, recommended additional investigations, and recommended capital works.

In the small box under the General Arrangement photograph is shown the AADT per legacy information, (or updated as the case may be), the number of available traffic lanes crossing the structure, the structure skew angle in degrees, and the general direction of the road that crosses the structure, for example E-W means East to West. Accompanying this information are the Latitude and Longitude at the centre of the structure expressed in decimal degrees. Also include is data where applicable or available for the road width, percent trucks, and any load posting.

Vital Statistics

On the bottom left of the front page of each inspection report is vital information that includes:

- ❖ Estimated Replacement Value
- ❖ Estimated Remaining Service Life
- ❖ Rehabilitation Year and Estimated Rehabilitation Cost (if applicable)

Bridge Condition

The bottom left of the front page provides a compelling graphical indication of the condition of the bridge with four key indicators:

- Bridge Condition Index
- Retained Value assuming Parabolic Depreciation
- Retained Value assuming Straight-Line Depreciation
- Loss of Structure Value due to Defect & Damage

These four indicators viewed together provide a very complete indication of the health and overall depreciation of the structure.

Component Inspection Information

The Component Inspection Information is recorded next. The number of components varies based on the complexity of the structure. In the left column for each component is listed:

- Component name in bold with the component count in parenthesis.
- The general category for the component in Italics.
- The Length, Width, Diameter, & Height of the component in metres based on legacy information, or field measure, and as appropriate.

Please note that measurements for substructure items are approximate only.

The second column of the Component Inspection Information captures the actual field inspection information for each component. Information is generally recorded on an exception basis. If there are no annotations it can be safely assumed that the component is generally in



satisfactory condition for its age. The following sub-headings explain in detail the inspection information:

Defects

Defects are relatively benign changes to a bridge component that cannot be attributed to simple aging. They result from a material Defect or lack of required maintenance. The amount of Defects is estimated to the nearest five percent based on visual inspection of all similar components included in the component count. For example, bridges have typically four wing walls, so the estimated defects are applied over all four wing walls. The Defects are characterized with a qualifying comment that is computer generated from drop-down lists in the Keystone Bridge Management System. Where Defects exceed 10%, they are highlighted in Yellow.

Damage

Damage is any change to a structure that alters its structural form, strength, or function. Damage may result from untended Defects. The Damage is estimated and reported analogous to Defects, except a level of accuracy of plus or minus 2% or better is maintained. Where Damage equals 5% to 10% it is highlighted in Amber. When Damage is equal to or greater than 10% it is highlighted in Red.

Red and amber flags appear to the right if damage is considered as critical or major respectively. This way an otherwise small amount of damage is brought to attention if the severity warrants it.

Maintenance

Maintenance recommendations are selected from a component specific drop-down menu in the Keystone Bridge Management System. Up to two maintenance recommendations can be selected and reported.

Capital Recommendation

Capital Recommendations are selected from a list of three options; Do Nothing, Repair, or Replace. The number of years in the future the Capital investment should take place is based on the inspector's best judgement, without considering the optimal timing for a comprehensive rehabilitation or replacement.

Remark

A remark field is populated from voice recorded comments generated when assessing the component.

Performance

If a component has a functional impairment, this may be noted in the Performance comment. The Performance comment is created through a context sensitive drop-down menu. The performance comment only appears when a performance defect has been identified.

Capital Needs Cost Estimate Breakdown

At the end of each Inspection Report is a section titled as per the above.



Capital costs estimates are automatically generated by the Keystone Bridge Management System for standard items which include:

- Deck Replacement
- Deck Concrete Overlay (O'Lay)
- Barrier Wall Replacement (B/Wall)
- Waterproof & Pave (WP&P)
- Expansion Joint (X-Jnt)

Unit prices for the above work are based on MTO and client supplied data and extensions are based on geometric data residing in the KBMS database. The unit costs are indicated on the form.

A 10% markup for contractor mobilization and general site work is surcharged to the base estimate. The Contract Administration & Contingencies is a straight 20% markup. The Estimated Traffic Management & Civil Items is usually included and is based on experience and the nature of the capital work.

Recommendations for additional investigations are included on the same page as the Capital Needs. A summary comment regarding the structure is included under the Inspection Comments heading.

At the bottom of the last page of each inspection report the BCI number, Straight-Line Depreciation percentage and Parabolic Depreciation percentage is expressed. Following these the Estimated Remaining Service Life and Estimated Replacement Cost is provided.

Inspection Images

All the photographs taken at the time of inspection are displayed six per page in the section immediately following the Inspection Report. The Image Number is displayed in the top-left corner of each photo. A brief caption is provided below each photo. For a more detailed look at a photo, the reduced images are available in digital format, in separate folders for each structure.

Also made available in digital format is a report indicating all the bridge image numbers and captions. In some instances, the caption is truncated due to lack of space on the printed report page. Reference to the Inspection Images Report will provide the full text of the caption.

Digital Copy

This entire report is reproduced in PDF format together with all the image files and will be made available through Dropbox or similar cloud services. Individual inspection reports are included in their own folder together with reduced images.

The original images are available on request, as well. The folder names correspond to the date of inspection. Keystone will maintain one copy of the original images on their file server for two years following the date of inspection.



Limitations

Keystone Bridge Management Corp. endeavours to provide valuable bridge asset management services that help its clients to prioritize and fund their bridge and large culvert capital and maintenance needs. Furthermore, we advise of structural performance deficiencies and attendant risks. In short, we help our clients sustain the life of their road structure inventory commensurate with economic and risk management considerations.

Decision Support

The information provided by Keystone should only be considered as a starting point in determining the fate of any given structure. Considerably more effort is required to meaningfully arrive at conclusive determinations respecting the management of any bridge or culvert. Keystone is a strong advocate of planning studies and life-cycle costing to establish a sound business case for all capital investments. As such, the information provided herein should only be considered as decision support information. Ultimately, the Owner must make the final determination for any of the recommendations given.

Other Caveats

Keystone provides these services in a fiercely competitive business environment. Our business value in terms of completing a routine biennial bridge inspection is to provide a competent highly experienced lead inspector and a student assistant. Our explicit attitude for the field work is “it takes as long as it takes.” The Client needs to understand however the following additional caveats with respect to the reporting provided herein:

1. Field measurements are only to an accuracy that reasonably supports depreciation modelling of the structure and should not be relied upon for any other purpose.
2. The inspection is mostly visual in nature and thus components of the structure that are not reasonably accessible due to depth of water, height, and the like will have a compromised assessment.
3. Ambient lighting and debris can hide or disguise defects and damage.
4. Heavy traffic will preclude a thorough inspection of deck surfaces.
5. Latent defects are not normally discoverable in a routine inspection.
6. There will always be inherent subjectivity when assessing defects and damage.
7. Cost estimates are based on average historical information and are not necessarily current or suitable for local conditions.
8. The comments provided are meant to augment the inspection observations. They are not intended to capture every nuance observed.
9. Where in our opinion the conventional visual inspection is insufficient to adequately and responsibly assess the structure, we will recommend follow-up investigations such as boat or ice access inspections, bridge deck condition surveys, and other enhanced inspection methods.



Closing


Keystone Bridge Management Corp. is pleased to report on the condition of the Township of South Stormont vehicle bridges and large culverts. Should there be any lingering concerns or additional information required with respect to this assignment, then Keystone will be happy to respond.

We trust the services rendered are complete, and in full keeping with the Terms of Reference. It is Keystone's sincerest desire that the recommendations stemming from this work will be helpful to the Township of South Stormont in keeping their structural inventory, safe, sound, serviceable, and sustainable. Keystone strives to help you get the most out of your road structure assets.


Harold Kleywegt, P.Eng.
Managing Director
Keystone Bridge Management Corp.




Structure Summary Statistics



Average Age	31.0
Youngest Age	1
Oldest Age	69
Structure Count	22



Average Deck Area	85 m ²
Min Deck Area	29 m ²
Max Deck Area	207 m ²
Total Deck Area	1,861 m²



Deck area < 20 yrs old	634 m ²
Deck area < 50 yrs old	1743 m ²
Deck area > 50 yrs old	118 m ²



Bridge List

Bridge ID	Name	Route	Length	Width	Spans	Const Yr
31-170	North Lunenburg Bridge	North Lunenburg Road	8.7	9.3	1	2008
31-175	Valade Road Bridge	Valade Rd.	21.4	6.3	1	1978
31-181	Red Bridge	Lefebvre Road	19.6	6.4	1	1978
31-182	McMillan Bridge	Delaney Road	21.8	9.5	1	2009
31-186	Kennedy Bridge	Delaney Road	11.3	9.0	1	2006
31-187	Campbell Bridge	McPhail Road	13.3	10.1	1	1988
31-208	Race Track Bridge	Barlow Road	5.6	5.1	1	1985
31-303	Shaver Bridge	Shaver Road	13.4	5.0	1	1950
31-A21	Johnson Bridge	Morgan Road	11.6	8.5	1	2007

Total # of Bridges 9

Those bridges where the span is highlighted in amber are not subject to the Ontario Statute for biennial inspection.



Culvert List

Culvert ID	Name	Route	Length	Span	Cells	Const Yr
C31-167	North Lunenburg Road Culvert	North Lunenburg Road, W	16.5	3.7	1	1978
C31-169	North Lunenburg Road Culvert	North Lunenburg Road, W	21.9	5.8	1	1974
C31-A01	Goldfield Road Culvert	Goldfield Road	22.1	3.8	1	2018
C31-A02	Hunters Road Culvert	Hunters Road	21.8	3.8	1	1976
C31-A03	Otto Road Culvert	Otto Road	17.2	3.6	1	2013
C31-A06	Beckstead Road Culvert	Beckstead Road	14.7	3.6	1	1980
C31-A08	Anderson Road Culvert	Anderson Road	12.2	4.2	1	1960
C31-A10	Finch-Osnabruck Boundary Rd Culve	Finch-Osnabruck Boundar	12.4	3.9	1	1995
C31-A12	Cooper Road Culvert	Cooper Road	21.7	4.8	1	1994
C31-A13	Wilburn Road Culvert	Wilburn Road	11.2	3.5	1	1990
C31-A15	MacRae Road Culvert	MacRae Road	18.2	3.3	1	1985
C31-A16	Northfield Road Culvert	Northfield Road	15.3	3.6	1	1990
C31-A18	O'Keefe Road Culvert	O'Keefe Road	17.2	3.2	1	1975

Total # of Culverts 13

Those culverts where the span is highlighted in amber are not subject to the Ontario Statute for biennial inspection.



Capital Needs Report

Year **2019**

Structure ID	Name	Route	Work	Cost
31-303	Shaver Bridge	Shaver Road	Abut Repairs	\$24,000
Sum for Year				\$24,000
Percentage of Grand Total				1.0%

Year **2020**

Structure ID	Name	Route	Work	Cost
C31-167	North Lunenburg Road Culvert	North Lunenburg Road, West	New Conc Culvert	\$327,000
C31-A10	Finch-Osnabruck Boundary Rd Culvert	Finch-Osnabruck Boundary Rd	Topping Slab	\$72,000
C31-A18	O'Keefe Road Culvert	O'Keefe Road	Guide rail	\$48,000
Sum for Year				\$447,000
Percentage of Grand Total				18.5%



Year 2021

Structure ID	Name	Route	Work	Cost
31-181	Red Bridge	Lefebvre Road	Misc Concrete Repairs, O'Lay, B/Wall, X-Jnt, Guide Rail	\$308,000
31-187	Campbell Bridge	McPhail Road	Guide Rail	\$47,000
C31-A02	Hunters Road Culvert	Hunters Road	New Conc Culvert	\$316,000
C31-A12	Cooper Road Culvert	Cooper Road	Guide Rail	\$36,000
			Sum for Year	\$707,000
			Percentage of Grand Total	29.3%

Year 2022

Structure ID	Name	Route	Work	Cost
31-175	Valade Road Bridge	Valade Rd.	Misc Concrete Repairs, O'Lay, B/Wall, X-Jnt, Guide Rail	\$319,000
31-208	Race Track Bridge	Barlow Road	B/Wall, Guide Rail	\$110,000
31-A21	Johnson Bridge	Morgan Road	WP&P	\$66,000
			Sum for Year	\$495,000
			Percentage of Grand Total	20.5%



Year 2023

Structure ID	Name	Route	Work	Cost
C31-A15	MacRae Road Culvert	MacRae Road	Concrete floor liner	\$36,000
				<hr/>
				Sum for Year \$36,000
				Percentage of Grand Total 1.5%


Year 2024

Structure ID	Name	Route	Work	Cost
C31-169	North Lunenburg Road Culvert	North Lunenburg Road, West	New Conc Culvert	\$446,000
C31-A06	Beckstead Road Culvert	Beckstead Road	New Conc Culvert	\$256,000
				<hr/>
				Sum for Year \$702,000
				Percentage of Grand Total 29.1%




Total Capital Needs (m's) \$2,411,000 Over 6 Years

Capital Expenditure by Year



Capital Expenditure by Structure Type



Bridge Maintenance Report

Bridge ID	Name	Road	Component	Maintenance
31-175	Valade Road Bridge	Valade Rd.	Embankment	Remove Brush/Trees
<i>Heavy brush around wing walls.</i>				
31-181	Red Bridge	Lefebvre Road	Delineator	Add Signs
<i>Delineators at SW & NE corners. Signs at NW & SE are missing.</i>				
			Embankment	Remove Brush/Trees
<i>Trees & brush require brushing out. Wild parsnip present.</i>				
31-182	McMillan Bridge	Delaney Road	Delineator	Add Signs Straighten Sign
<i>Delineator in the SW is missing. Sign in NE is bent.</i>				
			Embankment	Remove Brush/Trees
<i>Trees & brush around wing walls & under bridge should be cleared. Erosion at ends of curbs. Wild parsnip noted on embankments. Stone protection against abutment walls.</i>				
31-186	Kennedy Bridge	Delaney Road	Delineator	Adjust Height
<i>Signs are located at the ends of wing walls. Signs are set too low.</i>				
31-187	Campbell Bridge	McPhail Road	Steel Beam on Wood Post	Spot post replacement
<i>Many vehicle strikes. Four posts on north side of bridge damaged from vehicle impact, post anchors weakened from collision. Buried end treatments at all ends. Timber posts have varying degrees of decay, several posts require replacement.</i>				
			Delineator	Adjust Height
<i>Delineators at the ends of guide rail. Signs are set too low.</i>				
C31-A08	Anderson Road Culvert	Anderson Road	Embankment	Remove Brush/Trees
<i>Heavy vegetation growth. No guide rail or delineators at this site. Brush & trees at south end should be cleared.</i>				




Bridge ID	Name	Road	Component	Maintenance
C31-A10	Finch-Osnabruck Boundary Rd Culvert	Finch-Osnabruck Boundary Rd	Water Channel	Remove Obstructions
<i>West end of culvert partially blocked by fallen trees. Aggradation against the north wall inside barrel. Stagnant water</i>				
C31-A12	Cooper Road Culvert	Cooper Road	Embankment	Remove Brush/Trees
<i>Thick vegetation at culvert ends. Wild parsnip present. Tree in the SE corner should be cut back.</i>				
C31-A13	Wilburn Road Culvert	Wilburn Road	Water Channel	Remove Obstructions
<i>Stagnant flow. Large downed tree limb inside barrel.</i>				
			Embankment	Remove Brush/Trees
<i>Steep embankments. Wild parsnip present.</i>				
C31-A18	O'Keefe Road Culvert	O'Keefe Road	Embankment	Remove Brush/Trees
<i>Thick brush. Wild parsnip. Dry stone retaining wall in NW is partially failed.</i>				



Structure Replacement Costs

Bridge ID	Name	Estimated Remaining Service Life	Program Year	Estimated Replacement Cost
31-A21	Johnson Bridge	88	2022	\$485,000
31-182	McMillan Bridge	80		\$1,267,000
31-170	North Lunenburg Bridge	79		\$682,000
31-186	Kennedy Bridge	77		\$552,000
31-187	Campbell Bridge	69	2021	\$1,577,000
C31-A12	Cooper Road Culvert	65	2021	\$334,000
31-208	Race Track Bridge	56	2022	\$182,000
31-175	Valade Road Bridge	39	2022	\$992,000
31-181	Red Bridge	39	2021	\$925,000
C31-A01	Goldfield Road Culvert	39		\$250,000
C31-A03	Otto Road Culvert	34		\$543,000
C31-A08	Anderson Road Culvert	31		\$222,000
31-303	Shaver Bridge	16	2019	\$833,000
C31-A16	Northfield Road Culvert	16		\$194,000
C31-A10	Finch-Osnabruck Boundary Rd Culvert	11	2020	\$243,000
C31-A13	Wilburn Road Culvert	11		\$146,000
C31-A18	O'Keefe Road Culvert	11	2020	\$250,000
C31-A15	MacRae Road Culvert	6	2023	\$213,000
C31-169	North Lunenburg Road Culvert	5	2024	\$357,000
C31-A06	Beckstead Road Culvert	5	2024	\$219,000
C31-A02	Hunters Road Culvert	2	2021	\$274,000
C31-167	North Lunenburg Road Culvert	1	2020	\$278,000





Total Replacement Cost	\$11,018,000
Average Replacement Cost	\$500,818
Total Deck Area	1861 m²



Culvert Replacement Cost

Culvert ID	Name	Existing Culvert Type	Common Costs	Total Cost Concrete Replacement	Total Cost Steel Replacement	Existing Culvert Replacement Cost	Life-Cycle Cost Concrete Replacement	Life-Cycle Cost Steel Replacement
C31-167	North Lunenburg Road Culvert	Soil-Steel Structure	\$157,200	\$327,000	\$278,000	\$278,000	\$330,900	\$339,200
C31-169	North Lunenburg Road Culvert	Soil-Steel Structure	\$170,900	\$446,000	\$357,000	\$357,000	\$451,400	\$435,500
C31-A01	Goldfield Road Culvert	Soil-Steel Structure	\$130,400	\$282,000	\$250,000	\$250,000	\$285,400	\$305,000
C31-A02	Hunters Road Culvert	Soil-Steel Structure	\$147,500	\$316,000	\$274,000	\$274,000	\$319,800	\$334,300
C31-A03	Otto Road Culvert	Soil-Steel Structure	\$257,900	\$657,000	\$543,000	\$543,000	\$664,900	\$662,500
C31-A06	Beckstead Road Culvert	Soil-Steel Structure	\$130,500	\$256,000	\$219,000	\$219,000	\$259,100	\$267,200
C31-A08	Anderson Road Culvert	Concrete Culvert	\$110,500	\$222,000	\$189,000	\$222,000	\$224,700	\$230,600
C31-A10	Finch-Osnabruck Boundary Rd	Soil-Steel Structure	\$153,500	\$278,000	\$243,000	\$243,000	\$281,300	\$296,500
C31-A12	Cooper Road Culvert	Concrete Culvert	\$141,300	\$334,000	\$274,000	\$334,000	\$338,000	\$334,300
C31-A13	Wilburn Road Culvert	Soil-Steel Structure	\$84,300	\$161,000	\$146,000	\$146,000	\$162,900	\$178,100
C31-A15	MacRae Road Culvert	Soil-Steel Structure	\$116,900	\$246,000	\$213,000	\$213,000	\$249,000	\$259,900
C31-A16	Northfield Road Culvert	Soil-Steel Structure	\$107,900	\$224,000	\$194,000	\$194,000	\$226,700	\$236,700
C31-A18	O'Keefe Road Culvert	Soil-Steel Structure	\$153,300	\$273,000	\$250,000	\$250,000	\$276,300	\$305,000

Estimated cost is based on a new culvert of similar size.

Recorded values, Length, Width, Height, Fill Depth, # Lanes Over, Water Depth are used in the calculations.


Typical culvert works (dewatering, traffic, etc.) are estimated and totalled for each structure.

Total Number of Timber Structures: 0

Total Number of Steel Structures: 11

Total Number of Concrete Structures: 2

Total Cost of Culvert Replacement Based on Similar Size and Type: \$3,523,000




Parabolic & Straight Line Depreciation

(Does not include culverts)

Name	Bridge ID	Built	Value (New)	Damage/Defects		Present Val (Parab)		Present Val (S/L)	
North Lunenburg Bridge	31-170	2008	\$540,306	3.7%	\$19,834	92.9%	\$501,938	79.5%	\$429,500
Valade Road Bridge	31-175	1978	\$716,328	15.1%	\$108,120	44.4%	\$317,783	27.2%	\$194,899
Red Bridge	31-181	1978	\$639,499	12.5%	\$79,783	48.3%	\$308,972	28.2%	\$180,472
McMillan Bridge	31-182	2009	\$840,578	1.8%	\$14,768	94.9%	\$797,674	81.5%	\$685,065
Kennedy Bridge	31-186	2006	\$413,867	0.3%	\$1,213	93.6%	\$387,330	77.5%	\$320,784
Campbell Bridge	31-187	1988	\$362,980	3.5%	\$12,555	70.7%	\$256,557	47.7%	\$173,191
Race Track Bridge	31-208	1985	\$145,168	7.6%	\$11,059	70.6%	\$102,521	49.6%	\$72,036
Shaver Bridge	31-303	1950	\$278,029	16.9%	\$47,037	46.0%	\$127,963	37.1%	\$103,097
Johnson Bridge	31-A21	2007	\$430,692	5.6%	\$24,129	90.0%	\$387,506	74.8%	\$322,012
Grand Total			\$4,367,447	7.3%	\$318,498	73.0%	\$3,188,244	56.8%	\$2,481,056



Bridge Depreciation Forecast 1




Legend

- Parabolic: Parabolic Depreciation not including effects of Defects & Damage
- Parabolic DD: Parabolic Depreciation including effects of Defects & Damage
- Straight Line: Straight-Line Depreciation not including effects of Defects & Damage
- Strt Ln DD: Straight-Line Depreciation including effects of Defects & Damage



Bridge Depreciation Forecast 2




Legend

- Parabolic: Parabolic Depreciation not including effects of Defects & Damage
- Parabolic DD: Parabolic Depreciation including effects of Defects & Damage
- Straight Line: Straight-Line Depreciation not including effects of Defects & Damage
- Strt Ln DD: Straight-Line Depreciation including effects of Defects & Damage



Remaining Value of all Bridges




Key	Investment Description	Annual Amount
Invest 0	No Investment	\$0
Invest 1	Recommended Capital (Average)	\$44,000
Invest 2	0.75% Replacement Value	\$52,500
Invest 3	1.0% Replacement Value	\$70,000
Invest 4	1.5% Replacement Value	\$105,000



Culvert Depreciation Forecast

Remaining Value of all Culverts




Original & Depreciated Values

Original	Now	5	10	15	20
\$3,523,000	\$1,523,891	\$1,127,491	\$861,321	\$674,263	\$527,637



Average Culvert Depreciation with Investment

Remaining Value of all Culverts



<u>Key</u>	<u>Investment Description</u>	<u>Annual Amount</u>
Invest 0	No Investment	\$0
Invest 1	Recommended Capital (Average)	\$77,000
Invest 2	0.75% Replacement Value	\$30,000
Invest 3	1.0% Replacement Value	\$40,000
Invest 4	1.5% Replacement Value	\$60,000



Recommended Investigations

Bridge ID	Name	Deck Condition Survey	Enhanced Inspection	Underwater Investigation	Ice Inspection	Boat Inspection	Structure Evaluation	Load Posting	Planning Study
-----------	------	-----------------------------	------------------------	-----------------------------	-------------------	--------------------	-------------------------	-----------------	-------------------

No Recommended Investigations



Performance Deficiencies Report

Bridge ID	Name	Component	Deficiency
31-175	Valade Road Bridge	Delineator	Missing
		X- Joint Conventional	Leaking
31-181	Red Bridge	Delineator	Missing
		Embankment	Toxic Weeds
		Steel Beam on Wood Post	Weakened
31-182	McMillan Bridge	Embankment	Toxic Weeds
31-186	Kennedy Bridge	Delineator	Inadequate Height
31-187	Campbell Bridge	Delineator	Inadequate Height
		Steel Beam on Wood Post	Weakened
31-208	Race Track Bridge	Steel Post & Guide Rail	Weakened
31-303	Shaver Bridge	Water Channel	Lacking Freeboard
		Delineator	Obscured
		Steel Sliding Plate	Uneven Bearing
C31-167	North Lunenburg Road Culvert	Circular CS Plate Pipe	Settlement
C31-A02	Hunters Road Culvert	CS Plate Pipe Arch	Load Carrying Capacity
		Embankment	Toxic Weeds
C31-A06	Beckstead Road Culvert	CS Plate Pipe Arch	Insufficient Barrel Length
		Embankment	Toxic Weeds
C31-A12	Cooper Road Culvert	Embankment	Toxic Weeds
		Steel Beam on Wood Post	Inadequate Height
C31-A13	Wilburn Road Culvert	Embankment	Toxic Weeds
		CS Plate Pipe Arch	Insufficient Barrel Length
		Water Channel	Obstructed
C31-A15	MacRae Road Culvert	Embankment	Over-steepened



Bridge Condition Index Report

Bridge ID	Name	BCI	Program Year
31-170	North Lunenburg Bridge	84.7	
31-175	Valade Road Bridge	71.6	2022
31-181	Red Bridge	70.3	2021
31-182	McMillan Bridge	86.6	
31-186	Kennedy Bridge	83.6	
31-187	Campbell Bridge	73.0	2021
31-208	Race Track Bridge	74.1	2022
31-303	Shaver Bridge	74.5	2019
31-A21	Johnson Bridge	83.4	2022
C31-167	North Lunenburg Road Culvert	64.4	2020
C31-169	North Lunenburg Road Culvert	60.3	2024
C31-A01	Goldfield Road Culvert	98.8	
C31-A02	Hunters Road Culvert	61.9	2021
C31-A03	Otto Road Culvert	92.5	
C31-A06	Beckstead Road Culvert	57.1	2024
C31-A08	Anderson Road Culvert	74.5	
C31-A10	Finch-Osnabruck Boundary Rd Culvert	58.2	2020
C31-A12	Cooper Road Culvert	73.8	2021
C31-A13	Wilburn Road Culvert	57.5	
C31-A15	MacRae Road Culvert	64.8	2023
C31-A16	Northfield Road Culvert	60.3	
C31-A18	O'Keefe Road Culvert	62.5	2020

Total Number of Structures 22			
BCI < 50: 0	BCI Between 50 and 60: 3	BCI Between 60 and 70: 6	BCI Above 70: 13
Percent: 0	13.6%	27.3%	59.1%



Bridge Inspection Report

North Lunenburg Bridge

Road Name: North Lunenburg Road West
Site ID: 31-170
Structure Type: Conc Rigid Frame Precast
Owner: Township South Stormont
Built: 2008
Length: 8.7 m
Width: 9.3 m
Spans: 1
Span Arrange: 7.9
Feature Under: Navigable Channel
Crossing: Raisin River
Location: 100 m West of County Road 12

Inspection Date: August-21-19
Inspector: Steve Reid, C.E.T.
Assistant: Seamus Fisher, Eng Student

Comments:

The current condition of this bridge is good. Topping slab has open cracks, no delaminations at this time. It may be beneficial to seal the cracks in the topping slab to prevent the acceleration of damage to the deck.

Recommended Investigations:

No Special Investigations Recommended

Recommended Capital Works:

No Capital Works Recommendations


Estimated Replacement Value: \$682,000

Estimated replacement value is based on replacement in kind

Estimated Remaining Service Life: 79 Years



AADT: 200 **Latitude:** 45.06769300
Lanes: 2 **Longitude:** -74.96798700
Skew: 0 ° **Orientation:** N-S
Speed: 80 km/h **Road Width:** 8.5 m
Trucks **Load Posting:** No Posting



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

<p>Unprotected BSRC Deck (1)</p> <p><i>Topping Slab</i></p> <p>Length: 8.7 m</p> <p>Width: 8.5 m</p> <p>Height: 0.15 m</p>	<p>Defects 25.0% Minor Scaling</p> <p>Damage 1.0% Moderate Cracking, Minor Impact</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Wide open longitudinal & transverse cracks in deck surface. Surface is scaled. No delaminations found. Some minor damage at deck ends from plow.</i></p>
<p>Soffit (1)</p> <p><i>Deck Soffit</i></p> <p>Length: 8.7 m</p> <p>Width: 8.5 m</p> <p>Height:</p>	<p>Defects 1.0% Minor Staining</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Good condition. Some minor leach stains at precast joints.</i></p>
<p>Asphalt Wear Surf (1)</p> <p><i>Apr Wear Surface</i></p> <p>Length: 10 m</p> <p>Width: 8.5 m</p> <p>Height:</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Satisfactory condition. Asphalt padding next to deck ends due to minor settlement.</i></p>
<p>Conc Curb (2)</p> <p><i>Approach Curb</i></p> <p>Length: 9.2 m</p> <p>Width: 0.4 m</p> <p>Height: 0.25 m</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Good condition, steel guide posts anchored to top of curbs. Approach curbs located on wing walls.</i></p>
<p>Conc Curb (2)</p> <p><i>Curbs</i></p> <p>Length: 8.7 m</p> <p>Width: 0.4 m</p> <p>Height: 0.25 m</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Good condition, steel thrie beam posts anchored to top of curbs.</i></p>
<p>Steel Post & Guide Rail (4)</p> <p><i>Approach Barrier</i></p> <p>Length: 6 m</p> <p>Width:</p> <p>Height: 0.72 m</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Good condition, located on approaches. Eccentric loader end treatments at the SE & NW.</i></p>



Component Inspection Information

Thrie Beam G/R (2)

Barrier

Length: 8.7 m
Width:
Height: 0.72 m

Defects 0.0%
Damage 0.0%
Maintenance None
Capital Rec. None

Satisfactory condition. Steel post & thrie beam on bridge.

RC Abutment Wall (2)

Precast Wall

Length:
Width: 9.3 m
Height: 1.5 m

Defects 0.0%
Damage 1.0% **Minor Spalling**
Maintenance None
Capital Rec. None

Precast walls have some minor parging repairs. 3-sided sections were placed on top of concrete abutment walls without proper bearing, the stress is causing spalling at the base of the precast walls.

RC Abutment Wall (2)

Abutment Stem

Length:
Width: 9.3 m
Height: 3.2 m

Defects 1.0% **Minor Leaching Cracks**
Damage 0.0%
Maintenance None
Capital Rec. None

Small abutment walls supporting the precast 3-sided sections. Walls are in good condition, some leaching cracks.

RC Wing Walls (4)

Wing Walls

Length: 9.2 m
Width:
Height: 1.88 m

Defects 0.0%
Damage 0.0%
Maintenance None
Capital Rec. None

Good condition.

Water Channel (1)

Channel

Defects 0.0%
Damage 0.0%
Maintenance None
Capital Rec. None

Well centred.

Embankment (4)

Embankment

Defects 0.0%
Damage 0.0%
Maintenance None
Capital Rec. None

Bell attached to north side of structure. Well groomed on north side, thick vegetation growth on south side..



Image 30



North elevation

Image 23



East approach

Image 24



West approach

Image 25



Guide rail on wing walls

Image 26



Thrie beam on deck

Image 27



Exposed concrete deck



Image 28



South channel

Image 29



North channel

Image 31



East abutment wall

Image 32



West abutment wall

Image 33



Soffit (typical)

Image 34



South elevation





Bridge Inspection Report

Valade Road Bridge

Road Name: Valade Rd.
Site ID: 31-175
Structure Type: Prestressed Solid Slab
Owner: Township South Stormont
Built: 1978
Length: 21.4 m
Width: 6.3 m
Spans: 1
Span Arrange: 21.4
Feature Under: Navigable Channel
Crossing: Raisin River
Location: 0.1 km East of County Road 18, Con 6 Lot 19

Inspection Date: August-20-19
Inspector: Steve Reid, C.E.T.
Assistant: Seamus Fisher, Eng Student

Comments:

Topping slab and joints are due for replacement, curbs & barrier system should be installed to prevent the water runoff at deck edges that is damaging the exterior girders. Recommend new asphaltic plug joints.

Recommended Investigations:

No Special Investigations Recommended


Recommended Capital Works:

Misc Concrete Repairs, O'Lay, B/Wall, X-Jnt, Guide Rail

Estimated Replacement Value: \$992,000
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: 39 Years
Rehabilitation Year and Estimated Cost: 2022 \$319,000



AADT: N/A **Latitude:** 45.09048100
Lanes: 1 **Longitude:** -74.83533100
Skew: 0 ° **Orientation:** E-W
Speed: 80 km/h **Road Width:** 4.1 m
Trucks **Load Posting:** No Posting



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

<p>Unprotected BSRC Deck (1)</p> <p><i>Topping Slab</i></p> <p>Length: 21.4 m</p> <p>Width: 6.3 m</p> <p>Height:</p>	<p>Defects 50.0% Moderate Scaling</p> <p>Damage 5.0% Moderate Delamination, Moderate Cracking</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Many wide cracks & delaminations. Surface is scaled throughout. Deck does not have proper drainage. Evidence of several core samples from deck.</i></p>
<p>Soffit (1)</p> <p><i>Deck Soffit</i></p> <p>Length: 21.4 m</p> <p>Width: 6.3 m</p> <p>Height:</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Soffit is underside of box girders. See girder notes.</i></p>
<p>X- Joint Conventional (2)</p> <p><i>Expansion Joints</i></p> <p>Length: 6.3 m</p> <p>Width:</p> <p>Height:</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. Replace in 2 years</p> <p><i>Joints are partially paved over. Joints are leaking.</i></p>
<p>Steel Beam on Wood Post (</p> <p><i>Guide Rail</i></p> <p>Length: 87.5 m</p> <p>Width:</p> <p>Height: 0.8 m</p>	<p>Defects 0.0%</p> <p>Damage 15.0% Moderate Impact, Moderate Decay</p> <p>Maintenance None</p> <p>Capital Rec. Replace in 2 years</p> <p><i>Numerous areas of impact damage. Posts have moderate to major decay in top surface. Several timber spacer blocks are missing.</i></p>
<p>RC Box (5)</p> <p><i>Girders</i></p> <p>Length: 21.4 m</p> <p>Width: 1.2 m</p> <p>Height: 0.7 m</p>	<p>Defects 0.5% Minor Leaching Cracks, Minor Leaching/Seepage</p> <p>Damage 1.0% Moderate Delamination, Moderate Spalling</p> <p>Maintenance None</p> <p>Capital Rec. Repair in 2 years</p> <p><i>Mostly good condition with the exception of the exterior corners & the exterior face of the exterior girders. Lack of drainage from the deck & the leaking expansion joints have damaged the exterior girders. Minor delaminations on bottom of girders at east end due to leaking joint.</i></p>
<p>RC Abutment Wall (2)</p> <p><i>Abutment Stem</i></p> <p>Length:</p> <p>Width: 6.3 m</p> <p>Height: 1.7 m</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Good condition.</i></p>



Component Inspection Information

RC Ballast Wall (2) Ballast Wall Length: 6.3 m Width: Height: 0.85 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None Satisfactory condition.	
RC Wing Walls (4) Wing Walls Length: 2.9 m Width: Height: 1.2 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None Good condition.	
Laminated Rubber Brg (28) Abutment Bearings Length: Width: Height:	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None Limited views of bearings, visible bearings were in good condition.	Partial Inspection
Water Channel (1) Channel	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None No concerns.	
Embankment (4) Embankment	Defects 0.0% Damage 0.0% Maintenance Remove Brush/Trees Capital Rec. None Heavy brush around wing walls.	
Delineator (4) Signs Length: Width: Height:	Defects 0.0% Damage 25.0% Minor Missing Maintenance None Capital Rec. None Delineator at the SW end of guide rail is missing.	Perf Def: Missing



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	✓	m ²	20.0	\$500	\$10,000
<i>Deck Concrete Overlay</i>	✓	m ²	134.8	\$350	\$47,187
<i>Deck Replacement</i>	✗	m ²	134.8	\$2,000	\$0
<i>Barrier Wall Replacement</i>	✓	m	45.4	\$1,500	\$100,200
<i>Expansion Joint</i>	✓	m	12.6	\$3,000	\$37,800
<i>Waterproof & Pave</i>	✗	m ²	134.8	\$200	\$0
<i>Bearing Replacement</i>	✗	Count	10.0	\$5,000	\$0
<i>Approach Guide Rail</i>	✓	m	80.0	\$200	\$24,000

Other Work

\$0

Structural Items Subtotal	\$219,000
Mobilization General Sitework 10%	\$22,000
Estimated Traffic Management & Civil Items	\$25,000
Contract Admin & Contingencies 20%	\$53,000
Total Rehabilitation Cost Estimate	<i>\$319,000</i>

Recommended Capital Work Summary

Recommended Capital Year **2022**

Misc Concrete Repairs, O'LAY, B/Wall, X-Jnt, Guide Rail

Inspection Comments

Topping slab and joints are due for replacement, curbs & barrier system should be installed to prevent the water runoff at deck edges that is damaging the exterior girders. Recommend new asphaltic plug joints.



Image 65



South elevation

Image 56



West approach

Image 57



West expansion joint

Image 58



East approach

Image 59



East expansion joint

Image 60



Deck surface



Image 61



North guide rail on deck

Image 62



NE guide rail on approach

Image 63



NE guide rail post decay

Image 64



South channel

Image 66



South exterior spalling

Image 67



East abutment wall



Image 68



Soffit typ (girder bottoms)

Image 69



West abutment wall

Image 70



North channel

Image 71





North elevation

Image 72



SW exterior spalling





Bridge Inspection Report

Red Bridge

Road Name: *Lefebvre Road*
Site ID: *31-181*
Structure Type: *Prestressed Solid Slab*
Owner: *Township South Stormont*
Built: *1978*
Length: *19.6 m*
Width: *6.4 m*
Spans: *1*
Span Arrange: *19.6*
Feature Under: *Water*
Crossing: *Raisin River*
Location: *0.15 km North of County Rd 18, Con 6 Lot 7*

Inspection Date: *August-20-19*
Inspector: *Steve Reid, C.E.T.*
Assistant: *Seamus Fisher, Eng Student*

Comments:

This bridge is due for a major rehabilitation. Joints & barrier system are driving the need for rehab. Poor drainage from bridge is damaging exterior girders.

Recommended Investigations:

No Special Investigations Recommended


Recommended Capital Works:

Misc Concrete Repairs, O'LAY, B/Wall, X-Jnt, Guide Rail

Estimated Replacement Value: **\$925,000**
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: **39 Years**
Rehabilitation Year and Estimated Cost: **2021 \$308,000**



AADT: *N/A* **Latitude:** *45.10995300*
Lanes: *2* **Longitude:** *-74.77310700*
Skew: *0 °* **Orientation:** *N-S*
Speed: *80 km/h* **Road Width:** *5.2 m*
Trucks **Load Posting:** *No Posting*



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

RC Topping Slab (1)	Defects 0.0%	
Deck Surface	Damage 0.0%	
Length: 19.6 m	Maintenance None	
Width: 6.4 m	Capital Rec. None	
Height:	<i>Assumed concrete topping slab on top of box girders. Deck is covered with asphalt. Evidence of recent deck condition survey in asphalt. No proper drainage from deck runoff is off the edges of bridge.</i>	
Soffit (1)	Defects 0.0%	
Deck Soffit	Damage 5.0%	Minor Fire Spalls
Length: 19.6 m	Maintenance None	
Width: 6.4 m	Capital Rec. None	
Height:	<i>Soffit is the bottom of box girders. North end is stained (no spalling) due to fire pit under bridge.</i>	
Asphalt Wear Surf (1)	Defects 0.0%	
Wear Surface	Damage 5.0%	Moderate Cracking
Length: 19.6 m	Maintenance None	
Width: 5.2 m	Capital Rec. None	
Height:	<i>Numerous random cracks. Evidence of recent condition survey.</i>	
X- Joint Conventional (2)	Defects 0.0%	
Expansion Joints	Damage 10.0%	Major End Dam Breakage, Major Plow Gouging
Length: 6.4 m	Maintenance None	
Width:	Capital Rec. Replace in 2 years	
Height:	<i>Joint seals are over compressed. Tops of both ballast walls have major damage from winter plow. Armouring also has minor plow scrapes.</i>	
Steel Beam on Wood Post (Defects 0.0%	
Guide Rail	Damage 10.0%	Major Decay, Moderate Impact
Length: 42.5 m	Maintenance None	
Width:	Capital Rec. Replace in 2 years	Perf Def: Weakened
Height: 0.72 m	<i>Guide rail has many collision scrapes. One post is completely severed at NE end. 47 m (E) + 38 m (W)</i>	
RC Box (7)	Defects 5.0%	Moderate Staining, Minor Rust Staining
Girders	Damage 1.0%	Minor Delamination, Minor Fire Spalls
Length: 19.6 m	Maintenance None	
Width: 0.9 m	Capital Rec. None	
Height: 0.7 m	<i>Delaminated area on bottom of west girder. Spall on exterior of west girder. Lack of drainage from deck is causing damage to exterior girders. Staining on underside of girders at north end evident of camp fires under bridge.</i>	



Component Inspection Information

RC Abutment Wall (2) Abutment Stem Length: Width: 6.4 m Height: 2.7 m	Defects 20.0% Moderate Scaling, Minor Graffiti Damage 1.0% Minor Delamination, Minor Spalling Maintenance None Capital Rec. None <i>Abutments tops were recast. NW corner has spalls & delaminated areas under girder. Old walls have moderate scaling.</i>	
RC Ballast Wall (2) Ballast Wall Length: Width: 6.4 m Height: 0.8 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Unable to view.</i>	Not Inspected
RC Wing Walls (4) Wing Walls Length: 1.8 m Width: Height: 1.4 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Satisfactory condition.</i>	
Laminated Rubber Brg (2) Abutment Bearings Length: Width: Height:	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Only visible at corners of abutments, no concerns noted.</i>	Partial Inspection
Water Channel (1) Channel	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Stream well centered under bridge.</i>	
Embankment (4) Embankment	Defects 0.0% Damage 0.0% Maintenance Remove Brush/Trees Capital Rec. None <i>Trees & brush require brushing out. Wild parsnip present.</i>	Perf Def: Toxic Weeds



Component Inspection Information

Delineator (4)

Defects **0.0%**

Signs

Damage **50.0%** **Moderate Missing**

Length:

Maintenance **Add Signs**

Width:

Capital Rec. **None**

Perf Def: Missing

Height:

Delineators at SW & NE corners. Signs at NW & SE are missing.



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	✓	m ²	20.0	\$500	\$10,000
<i>Deck Concrete Overlay</i>	✓	m ²	125.4	\$350	\$43,904
<i>Deck Replacement</i>	✗	m ²	125.4	\$2,000	\$0
<i>Barrier Wall Replacement</i>	✓	m	43.6	\$1,500	\$94,800
<i>Expansion Joint</i>	✓	m	12.8	\$3,000	\$38,400
<i>Waterproof & Pave</i>	✗	m ²	125.4	\$200	\$0
<i>Bearing Replacement</i>	✗	Count	14.0	\$5,000	\$0
<i>Approach Guide Rail</i>	✓	m	80.0	\$200	\$24,000

Other Work

\$0

Structural Items Subtotal	\$211,000
Mobilization General Sitework 10%	\$21,000
Estimated Traffic Management & Civil Items	\$25,000
Contract Admin & Contingencies 20%	\$51,000
Total Rehabilitation Cost Estimate	<i>\$308,000</i>

Recommended Capital Work Summary

Recommended Capital Year

2021

Misc Concrete Repairs, O' Lay, B/Wall, X-Jnt, Guide Rail

Inspection Comments

This bridge is due for a major rehabilitation. Joints & barrier system are driving the need for rehab. Poor drainage from bridge is damaging exterior girders.



Image 40



West elevation

Image 26



South approach

Image 27



North approach

Image 28



North expansion joint

Image 29



West guide rail on deck

Image 30



South expansion joint



Image 31



Asphalt on deck

Image 32



West channel

Image 33



East channel

Image 34



NW guide rail impact damage

Image 35



NE guide rail post severed

Image 36



North abutment wall



Image 37



Soffit typ (girder bottoms)

Image 38




South abutment wall

Image 39



East elevation

Image 41



NW corner typ damage at corners

Image 42



North soffit fire damage

Image 43



West exterior girder delamination



Bridge Inspection Report

McMillan Bridge

Road Name: *Delaney Road*
Site ID: *31-182*
Structure Type: *Slab on Steel Girder*
Owner: *Township South Stormont*
Built: *2009*
Length: *21.8 m*
Width: *9.5 m*
Spans: *1*
Span Arrange: *19.2*
Feature Under: *Navigable Channel*
Crossing: *Raisin River*
Location: *0.5km North of County Rd 18, Lot 1, Concession 6,*

Inspection Date: *August-20-19*
Inspector: *Steve Reid, C.E.T.*
Assistant: *Seamus Fisher, Eng Student*

Comments:
Current condition of this bridge is good, minor maintenance recommended at this time.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
No Capital Works Recommendations

Estimated Replacement Value: *\$1,267,000*
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: *80 Years*



AADT: *22* **Latitude:** *45.12453600*
Lanes: *2* **Longitude:** *-74.76022500*
Skew: *0 °* **Orientation:** *N-S*
Speed: *80 km/h* **Road Width:** *8.5 m*
Trucks **Load Posting:** *No Posting*



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

<p>Unprotected BSRC Deck (1)</p> <p><i>Deck Surface</i></p> <p>Length: 21.8 m</p> <p>Width: 9.5 m</p> <p>Height: 0.23 m</p>	<p>Defects 10.0% Minor Scaling, Minor Scrapes/Gouging</p> <p>Damage 0.1% Minor Cracking</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Most of tining has been lost. Minor plow gouging at north end. Transverse cracks at north end. Scaling of exposed concrete surface.</i></p>
<p>Soffit (1)</p> <p><i>Deck Soffit</i></p> <p>Length: 21.8 m</p> <p>Width: 8.4 m</p> <p>Height:</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Pristine.</i></p>
<p>Approach Slab (2)</p> <p><i>Approach Slab</i></p> <p>Length: 6 m</p> <p>Width: 9.5 m</p> <p>Height:</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Tining has mostly worn off. Surface treatment extends partially on to approach slabs.</i></p>
<p>Asphalt Wear Surf (1)</p> <p><i>Appr Wear Surface</i></p> <p>Length: 10 m</p> <p>Width: 9.5 m</p> <p>Height:</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Surface treatment on approaches to bridge.</i></p>
<p>Conc Curb (2)</p> <p><i>Curbs</i></p> <p>Length: 29.2 m</p> <p>Width: 0.59 m</p> <p>Height: 0.15 m</p>	<p>Defects 2.0% Minor Scaling</p> <p>Damage 0.5% Minor Cracking</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Curbs have a very poor finish. Many transverse cracks in top of curbs. Curb on SE wing wall appears to be in the worst condition.</i></p>
<p>Steel Beam on Steel Post (2)</p> <p><i>Guide Rail</i></p> <p>Length: 102.4 m</p> <p>Width:</p> <p>Height: 0.72 m</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Eccentric loader end treatment at all guide rail ends. Erosion at corners of bridge have exposed guide rail posts next to end walls. 94.20 m (W) + 110.60 m €</i></p>



Component Inspection Information

Steel Beam (20) Diaphragms Length: 2.1 m Width: 0.165 m Height: 0.31 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Good condition.</i>	
Thrie Beam G/R (2) Barrier Length: 29.2 m Width: Height: 0.69 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Thrie beams are mounted on the bridge curbs, condition.is good.</i>	
Steel-Fabricated (5) Girders Length: 19.6 m Width: 0.292 m Height: 0.84 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Girders are in good condition. Ends of girders are nicely coated.</i>	
RC Abutment Wall (2) Abutment Stem Length: Width: 9.3 m Height: 3.65 m	Defects 1.0% Minor Graffiti, Minor Scaling Damage 0.0% Maintenance None Capital Rec. None <i>Some areas of poor segregation of concrete on north wall. Graffiti on both walls mainly south. Rip rap against walls.</i>	
RC Ballast Wall (2) Ballast Wall Length: Width: 9.3 m Height: 0.58 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Semi-integral abutments.</i>	Not Inspected
RC Wing Walls (4) Wing Walls Length: 5.3 m Width: Height: 2.6 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Good condition.</i>	



Component Inspection Information

Laminated Rubber Brg (10) Defects **0.0%**
Abutment Bearings Damage **0.0%**
 Length: Maintenance **None**
 Width: Capital Rec. **None**
 Height: *Satisfactory condition.*

Water Channel (1) Defects **0.0%**
Channel Damage **0.0%**
 Maintenance **None**
 Capital Rec. **None**
Water moving well under bridge.

Embankment (4) Defects **5.0%** **Moderate Erosion**
Embankment Damage **0.0%**
 Maintenance **Remove Brush/Trees**
 Capital Rec. **None** Perf Def: **Toxic Weeds**
*Trees & brush around wing walls & under bridge should be cleared.
 Erosion at ends of curbs. Wild parsnip noted on embankments. Stone
 protection against abutment walls.*

Delineator (2) Defects **0.0%**
Signs Damage **30.0%** **Moderate Missing, Minor Impact**
 Length: Maintenance **Add Signs, Straighten Sign**
 Width: Capital Rec. **None**
 Height: *Delineator in the SW is missing. Sign in NE is bent.*



Image 25



East elevation

Image 14



North approach

Image 15



South approach

Image 16



SE guide rail on approach

Image 17



East thrie beam on deck

Image 18



East channel



Image 19



Deck surface

Image 20



West channel

Image 21




North end deck cracking

Image 22




North abutment wall

Image 23



Soffit typ

Image 24



South abutment wall



Bridge Inspection Report

Kennedy Bridge

Road Name: *Delaney Road*
Site ID: *31-186*
Structure Type: *Precast Arch*
Owner: *Township South Stormont*
Built: *2006*
Length: *11.3 m*
Width: *9 m*
Spans: *1*
Span Arrange: *11*
Feature Under: *Water*
Crossing: *North Raisin River*
Location: *75m South of McPhail Rd, Lot 1 Concession 7,*

Inspection Date: *July-05-19*
Inspector: *Steve Reid, C.E.T.*
Assistant: *Seamus Fisher, Eng Student*

Comments:
Structure is in overall good condition. The approach guide rail will need updating within 10 years.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
No Capital Works Recommendations

Estimated Replacement Value: *\$552,000*
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: *77 Years*



AADT: *200* **Latitude:** *45.14623900*
Lanes: *2* **Longitude:** *-74.77131600*
Skew: *0 °* **Orientation:** *N-S*
Speed: *80 km/h* **Road Width:** *7.6 m*
Trucks **Load Posting:** *No Posting*



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

Precast Concrete Arch (1)	Defects 0.5%	Minor Graffiti, Minor Formed Patches
Conduit	Damage 0.0%	
Length: 11 m	Maintenance None	
Width: 9 m	Capital Rec. None	
Height: 3.1 m	<i>Overall very good condition. Graffiti on the south wall. Small repair in soffit, likely due to handling spall.</i>	
RC Topping Slab (1)	Defects 0.0%	
Deck Surface	Damage 0.0%	
Length: 11.3 m	Maintenance None	
Width: 9 m	Capital Rec. None	
Height:	<i>Covered with asphalt, suspect no problems on deck.</i>	
Asphalt Wear Surf (1)	Defects 0.0%	
Wear Surface	Damage 0.0%	
Length: 11.3 m	Maintenance None	
Width: 7.6 m	Capital Rec. None	
Height:	<i>Good condition.</i>	
Conc Curb (2)	Defects 0.0%	
Curbs	Damage 0.0%	
Length: 11.8 m	Maintenance None	
Width: 0.4 m	Capital Rec. None	
Height: 0.1 m	<i>Good condition. Thrie beam posts secured to curb tops.</i>	
Steel Beam on Steel Post (4)	Defects 0.0%	
Guide Rail	Damage 1.0%	Minor Impact
Length: 24.5 m	Maintenance None	
Width:	Capital Rec. None	
Height: 0.72 m	<i>Buried ends in the NE & SW, eccentric loader end treatment in the NW & SE. Several areas of impact damage to approach guide rail.</i>	
Thrie Beam G/R (2)	Defects 0.0%	
Barrier	Damage 0.0%	
Length: 11 m	Maintenance None	
Width:	Capital Rec. None	
Height: 0.72 m	<i>Good condition. Thrie beam over bridge, secured to steel posts.</i>	



Component Inspection Information

<p>RC Wing Walls (4)</p> <p><i>Wing Walls</i></p> <p>Length: 7 m</p> <p>Width: 0.25 m</p> <p>Height: 2.4 m</p>	<p>Defects 1.0% Minor Scaling</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Good condition. Some light scaling on the SW wall.</i></p>
<p>Headwall (2)</p> <p><i>Head Wall</i></p> <p>Length: 11.3 m</p> <p>Width:</p> <p>Height: 1 m</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Headwalls have varied height. West headwall has small area of damage, appears to have been done at time of construction.</i></p>
<p>Water Channel (1)</p> <p><i>Channel</i></p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Good condition.</i></p>
<p>Embankment (4)</p> <p><i>Embankment</i></p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Large stone protection at ends of wing walls. Embankments are in good condition.</i></p>
<p>Delineator (4)</p> <p><i>Signs</i></p> <p>Length:</p> <p>Width:</p> <p>Height:</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance Adjust Height</p> <p>Capital Rec. None</p> <p>Perf Def: Inadequate Height</p> <p><i>Signs are located at the ends of wing walls. Signs are set too low.</i></p>



Image 23



West elevation

Image 15



South approach

Image 16



North approach

Image 17



NW guide rail system

Image 18



Thrie beam over bridge typ

Image 19



East channel



Image 20



West channel

Image 21



Impact damage NW end

Image 22



NW wing wall typ

Image 24



North abutment wall

Image 25



South abutment wall

Image 26



Soffit (typical)



Image 27



Small repaired area in soffit

Image 28



East elevation



Bridge Inspection Report

Campbell Bridge

Road Name: *McPhail Road*
Site ID: *31-187*
Structure Type: *Concrete Rigid Frame CIP*
Owner: *Township South Stormont*
Built: *1988*
Length: *13.3 m*
Width: *10.1 m*
Spans: *1*
Span Arrange: *12*
Feature Under: *Water*
Crossing: *North Raisin River*
Location: *5km East of Hwy. 138, Lot 1, Concession 7 & 8,*

Inspection Date: *July-05-19*
Inspector: *Steve Reid, C.E.T.*
Assistant: *Seamus Fisher, Eng Student*

Comments:

Bridge is in very good condition. Lack of proper drainage from bridge will likely result in damage to soffit on the south side. Guide rail has many areas of collision damage due to the curved road alignment at bridge. Buried end treatments do not meet the current standards. Due to the damage and performance deficiencies recommend the guide rail be replaced within two years.

Recommended Investigations:

No Special Investigations Recommended


Recommended Capital Works:

Guide Rail

Estimated Replacement Value: *\$1,577,000*
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: *69 Years*
Rehabilitation Year and Estimated Cost: *2021 \$47,000*



AADT: *960* **Latitude:** *45.14823400*
Lanes: *2* **Longitude:** *-74.77434500*
Skew: *20 °* **Orientation:** *E-W*
Speed: *80 km/h* **Road Width:** *8.8 m*
Trucks **Load Posting:** *No Posting*



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation % retained value

SLD = Straight Line Depreciation % retained value

DD = Defects and Damage % loss of retained value



Component Inspection Information

RC Topping Slab (1)	Defects 0.0%	
Deck Surface	Damage 0.1%	Minor Cracking
Length: 13.3 m	Maintenance None	
Width: 10.1 m	Capital Rec. None	
Height:	<i>Covered with skim coat of asphalt. Shoulder areas are exposed. Chain drag in 2019 detected no delaminations. Crack noted in NW corner. Tining is present on exposed deck.</i>	
Soffit (1)	Defects 0.0%	
Deck Soffit	Damage 0.5%	Minor Delamination, Minor Cracking
Length: 12 m	Maintenance None	
Width: 10.1 m	Capital Rec. None	
Height:	<i>Overall very good condition. Some cracking in soffit. Minor delaminated areas along south edge. Lack of proper drainage from deck is causing damage at south edge.</i>	
Asphalt Wear Surf (1)	Defects 0.0%	
Wear Surface	Damage 0.0%	
Length: 13.3 m	Maintenance None	
Width: 6.5 m	Capital Rec. None	
Height:	<i>Satisfactory condition. Thin skim coat on deck.</i>	
Steel Beam on Wood Post (Defects 0.0%	
Guide Rail	Damage 10.0%	Moderate Impact, Moderate Decay
Length: 40 m	Maintenance Spot post replacement	
Width:	Capital Rec. None	Perf Def: Weakened
Height: 0.5 m	<i>Many vehicle strikes. Four posts on north side of bridge damaged from vehicle impact, post anchors weakened from collision. Buried end treatments at all ends. Timber posts have varying degrees of decay, several posts require replacement.</i>	
RC Abutment Wall (2)	Defects 5.0%	Minor Leaching Cracks, Minor Honeycomb, Minor Graffiti
Abutment Stem	Damage 0.5%	Minor Cracking
Length:	Maintenance None	
Width: 10.1 m	Capital Rec. None	
Height: 2.3 m	<i>Overall good condition. Some vertical moderate cracks. Minor leaching cracks. Small pocket honeycomb on east wall. West wall is stained on lower portion. Graffiti on west wall. Founded on bedrock.</i>	



Component Inspection Information

RC Wing Walls (4)

Wing Walls

Length: 6 m

Width:

Height: 1.4 m

Defects **0.1%** **Minor Leaching/Seepage**

Damage **0.0%**

Maintenance **None**

Capital Rec. **None**

Overall good condition. Some leaching at exterior knee joints.

Rip Rap (4)

Channel Armour

Defects **0.0%**

Damage **0.0%**

Maintenance **None**

Capital Rec. **None**

No concerns.

Water Channel (1)

Channel

Defects **0.0%**

Damage **0.0%**

Maintenance **None**

Capital Rec. **None**

Good condition.

Embankment (4)

Embankment

Defects **0.0%**

Damage **0.0%**

Maintenance **None**

Capital Rec. **None**

Good condition. Wild parsnip is present. Some tree growth near wing walls.

Delineator (4)

Signs

Length:

Width:

Height:

Defects **0.0%**

Damage **0.0%**

Maintenance **Adjust Height**

Capital Rec. **None**

Perf Def: Inadequate Height

Delineators at the ends of guide rail. Signs are set too low.



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	X	m ²	0.0	\$500	\$0
<i>Deck Concrete Overlay</i>	X	m ²	134.3	\$350	\$0
<i>Deck Replacement</i>	X	m ²	134.3	\$2,000	\$0
<i>Barrier Wall Replacement</i>	X	m	37.3	\$1,500	\$0
<i>Expansion Joint</i>	X	m	20.2	\$3,000	\$0
<i>Waterproof & Pave</i>	X	m ²	134.3	\$200	\$0
<i>Bearing Replacement</i>	X	Count	0.0	\$5,000	\$0
<i>Approach Guide Rail</i>	✓	m	80.0	\$200	\$24,000

Other Work

\$0

Structural Items Subtotal	\$24,000
Mobilization General Sitework 10%	\$10,000
Estimated Traffic Management & Civil Items	\$5,000
Contract Admin & Contingencies 20%	\$8,000
Total Rehabilitation Cost Estimate	<i>\$47,000</i>

Recommended Capital Work Summary

Recommended Capital Year

2021

Guide Rail

Inspection Comments

Bridge is in very good condition. Lack of proper drainage from bridge will likely result in damage to soffit on the south side. Guide rail has many areas of collision damage due to the curved road alignment at bridge. Buried end treatments do not meet the current standards. Due to the damage and performance deficiencies recommend the guide rail be replaced within two years.



Image 8



South elevation

Image 1



East approach

Image 2



West approach

Image 3



Barrier system north side

Image 4



North channel

Image 5



South channel



Image 6



Asphalt on deck

Image 7



Typ decay in post tops

Image 9



East abutment wall

Image 10



Soffit (typical)

Image 11



West abutment wall

Image 12



North elevation



Image 13




Delams soffit south side

Image 14



SW corner detail





Bridge Inspection Report

Race Track Bridge

Road Name: *Barlow Road*
Site ID: *31-208*
Structure Type: *Slab on Steel Girder*
Owner: *Township South Stormont*
Built: *1985*
Length: *5.6 m*
Width: *5.12 m*
Spans: *1*
Span Arrange: *5.1*
Feature Under: *Water*
Crossing: *South Raisin River*
Location: *1km East of County Rd 33. Lot 17, Concession 4.*

Inspection Date: *August-20-19*
Inspector: *Steve Reid, C.E.T.*
Assistant: *Seamus Fisher, Eng Student*

Comments:
With the exception of the curbs and barrier system this small bridge is performing well. New curbs and barrier are needed.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
B/Wall, Guide Rail

Estimated Replacement Value: *\$182,000*
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: *56 Years*
Rehabilitation Year and Estimated Cost: *2022 \$110,000*



AADT: *N/A* **Latitude:** *45.05443800*
Lanes: *1* **Longitude:** *-74.80034900*
Skew: *0 °* **Orientation:** *N-S*
Speed: *50 km/h* **Road Width:** *4.84 m*
Trucks **Load Posting:** *No Posting*



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

Soffit (1)	Defects 0.0%	
Deck Soffit	Damage 0.0%	
Length: 5.62 m	Maintenance None	
Width: 5.12 m	Capital Rec. None	
Height:	<i>Satisfactory condition.</i>	
Timber Wear Surface (1)	Defects 0.0%	
Wear Surface	Damage 2.0%	Minor Wear, Minor Gouging
Length: 5.62 m	Maintenance None	
Width: 5.12 m	Capital Rec. None	
Height:	<i>Partially covered with gravel, west side is exposed. Top of exposed timbers have minor damage from winter plow.</i>	
Armouring (2)	Defects 0.0%	
Expansion Joints	Damage 0.0%	
Length: 5.12 m	Maintenance None	Not Inspected
Width:	Capital Rec. None	
Height:	<i>Covered with gravel.</i>	
Timber Curb (2)	Defects 10.0%	Moderate Bowed/Warped
Curbs	Damage 10.0%	Moderate Breakage
Length: 5.62 m	Maintenance None	
Width: 0.14 m	Capital Rec. Replace in 2 years	
Height: 0.16 m	<i>Curb on east side is mostly missing. West side is comprised of 3 2x8 boards. Boards have pulled up at north end.</i>	
Steel Post & Guide Rail (4)	Defects 0.0%	
Approach Barrier	Damage 30.0%	Moderate Impact
Length: 15.6 m	Maintenance None	
Width:	Capital Rec. Replace in 1 year	Perf Def: Weakened
Height: 0.72 m	<i>Many impact strikes on flex beam. Post spacing not up to standard. 15.2 m (N) + 16.0 m (S)</i>	
Steel Beam on Wood Post (Defects 0.0%	
Guide Rail	Damage 20.0%	Moderate Impact, Major Decay
Length: 5.6 m	Maintenance None	
Width:	Capital Rec. Replace in 1 year	
Height: 0.72 m	<i>Major collision damage to both sides of guide rail barrier. Timber posts have major decay in top surface. Post spacing is not up to standard.</i>	



Component Inspection Information

Steel-Fabricated (7) Girders Length: 5.1 m Width: 0.205 m Height: 0.31 m	Defects 2.0% Minor Tarnishing Damage 0.0% Maintenance None Capital Rec. None <i>Good condition. Girder ends are embedded in concrete abutment walls.</i>
RC Abutment Wall (2) Abutment Stem Length: Width: 6.7 m Height: 1.94 m	Defects 5.0% Moderate AAR Cracking, Minor Honeycomb, Minor Erosion Damage 0.0% Maintenance None Capital Rec. None <i>Minor honeycomb in the NW face, small pocket of erosion in the SE face. Exterior edges have AAR open cracking.</i>
RC Wing Walls (4) Wing Walls Length: 1.55 m Width: Height: 1.1 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Satisfactory condition.</i>
Rip Rap (1) Slope Protection Length: Width: Height:	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>No concerns.</i>
Water Channel (1) Channel	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Accumulation of stones at the west upstream side of bridge. Minor scour at south abutment. Water moving well under bridge.</i>
Embankment (4) Embankment	Defects 5.0% Minor Erosion Damage 0.0% Maintenance None Capital Rec. None <i>Embankments at the corners of the bridge are slipping down into channel.</i>



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	x	m ²	0.0	\$500	\$0
<i>Deck Concrete Overlay</i>	x	m ²	28.7	\$350	\$0
<i>Deck Replacement</i>	x	m ²	28.7	\$2,000	\$0
<i>Barrier Wall Replacement</i>	✓	m	29.6	\$1,500	\$52,800
<i>Expansion Joint</i>	x	m	10.2	\$3,000	\$0
<i>Waterproof & Pave</i>	x	m ²	28.7	\$200	\$0
<i>Bearing Replacement</i>	x	Count	14.0	\$5,000	\$0
<i>Approach Guide Rail</i>	✓	m	80.0	\$200	\$24,000

Other Work

\$0

Structural Items Subtotal	\$77,000
Mobilization General Sitework 10%	\$10,000
Estimated Traffic Management & Civil Items	\$5,000
Contract Admin & Contingencies 20%	\$18,000
Total Rehabilitation Cost Estimate	<i>\$110,000</i>

Recommended Capital Work Summary

Recommended Capital Year

2022

B/Wall, Guide Rail

Inspection Comments

With the exception of the curbs and barrier system this small bridge is performing well. New curbs and barrier are needed.



Image 8



East elevation

Image 1



South approach

Image 2



North approach

Image 3



East guide rail on bridge

Image 4



SE guide rail impact damage

Image 5



East channel



Image 6



West channel

Image 7



Gravel on timber deck

Image 9



South abutment wall

Image 11



Soffit typ

Image 12



North abutment wall

Image 13



West guide post decay



Bridge Inspection Report

Shaver Bridge

Road Name: *Shaver Road*
Site ID: *31-303*
Structure Type: *Truss-Half Through*
Owner: *Township South Stormont*
Built: *1950*
Length: *13.4 m*
Width: *5 m*
Spans: *1*
Span Arrange: *12.2*
Feature Under: *Water*
Crossing: *Hoople Creek*
Location: *0.8km N of Colonial Rd, Lot 12 & 13, Concession 11*

Inspection Date: *August-21-19*
Inspector: *Steve Reid, C.E.T.*
Assistant: *Seamus Fisher, Eng Student*

Comments:

Construction year was estimated at 1950. This bridge is unsafe due to the loss of support under the south bearings. Bridge bearing in SE corner is of major concern, loss of concrete in SE corner has left bearing unstable, SW similar but not as bad. Condition of bridge was brought to owners attention, immediate repairs are needed.

Recommended Investigations:

No Special Investigations Recommended


Recommended Capital Works:

Abut Repairs

Estimated Replacement Value: **\$833,000**
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: **16 Years**
Rehabilitation Year and Estimated Cost: **2019 \$24,000**



AADT: *200* **Latitude:** *45.01440800*
Lanes: *1* **Longitude:** *-74.95646600*
Skew: *0 °* **Orientation:** *N-S*
Speed: *80 km/h* **Road Width:** *4.7 m*
Trucks **Load Posting:** *10 tonne*



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

Unprotected BSRC Deck (1) Defects **0.0%**
Deck Surface Damage **0.0%**
 Length: **13.35 m** Maintenance **None**
 Width: **5.1 m** Capital Rec. **None**
 Height: **0.18 m** *Good condition. Some granular materials from approaches have migrated onto deck.*

Soffit (1) Defects **0.5%** **Minor Leaching/Seepage**
Deck Soffit Damage **0.0%**
 Length: **13.35 m** Maintenance **None**
 Width: **5.04 m** Capital Rec. **None**
 Height: **0.175 m** *Satisfactory condition.*

Strip Seal (2) Defects **0.0%**
Expansion Joints Damage **0.0%**
 Length: **5 m** Maintenance **None**
 Width: Capital Rec. **None**
 Height: *Good condition.*

Conc Curb (2) Defects **0.1%** **Minor Leaching Cracks**
Curbs Damage **0.0%**
 Length: **13.35 m** Maintenance **None**
 Width: **0.15 m** Capital Rec. **None**
 Height: **0.15 m** *Good condition. Some minor leaching cracks.*

Steel Beam on Steel Post (2) Defects **0.0%**
Guide Rail Damage **0.0%**
 Length: **31 m** Maintenance **None**
 Width: Capital Rec. **None**
 Height: **0.72 m** *Guide rail is overgrown with vegetation. Guide rail on bridge is attached to new verticals supports attached to the exterior deck curb fascia & floor beams.*

Top Chord (2) Defects **0.0%**
Top Chord Damage **0.0%**
 Length: **9.2 m** Maintenance **None**
 Width: **0.08 m** Capital Rec. **None**
 Height: **0.08 m** *Satisfactory condition.*



Component Inspection Information

Bottom Chord (2)	Defects 0.0%
Bottom Chord	Damage 2.0% Moderate Deformation
Length: 13.3 m	Maintenance None
Width: 0.08 m	Capital Rec. None
Height: 0.08 m	<i>Damaged in several locations. Built up angle sections.</i>
<hr/>	
Diagonal/Post/Hangar (12)	Defects 0.0%
Diagonals/Hangars	Damage 0.0%
Length: 3.1 m	Maintenance None
Width: 0.07 m	Capital Rec. None
Height: 0.07 m	<i>Satisfactory condition.</i>
<hr/>	
Stringers (36)	Defects 0.0%
Steel Stringer	Damage 0.0%
Length: 6.7 m	Maintenance None
Width: 0.04 m	Capital Rec. None
Height: 0.25 m	<i>Satisfactory condition.</i>
<hr/>	
Bailey Bottom Bracing (6)	Defects 0.0%
Bracing	Damage 2.0% Moderate Deformation
Length: 6.7 m	Maintenance None
Width: 0.06 m	Capital Rec. None
Height: 0.08 m	<i>Several bent members.</i>
<hr/>	
Steel Floor Beam (6)	Defects 0.0%
Connections	Damage 0.0%
Length:	Maintenance None
Width:	Capital Rec. None
Height:	<i>Satisfactory condition. Limited view of several connections due to high water.</i>
<hr/>	
Steel Floor Beam (2)	Defects 0.0%
Floor Beams	Damage 0.0%
Length: 5.23 m	Maintenance None
Width: 0.082 m	Capital Rec. None
Height: 0.53 m	<i>Satisfactory condition. Limited view due to high water.</i>



Component Inspection Information

RC Abutment Wall (2) Abutment Stem Length: Width: 5.04 m Height: 1.2 m	Defects 0.0% Damage 30.0% Moderate Disintegration, Critical Disintegration Maintenance None Capital Rec. None <i>South abutment has major disintegration, north abutment minor disintegration. Loss of support at SE corner under bearing is very concerning.</i>
RC Ballast Wall (2) Ballast Wall Length: Width: 5.04 m Height: 0.67 m	Defects 0.0% Damage 2.0% Moderate Disintegration Maintenance None Capital Rec. None <i>Disintegration noted at south end.</i>
RC Wing Walls (4) Wing Walls Length: 2.3 m Width: 0.3 m Height: 0.43 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Good condition.</i>
Steel Sliding Plate (4) Abutment Bearings Length: Width: Height:	Defects 0.0% Damage 50.0% Critical Section Loss Maintenance None Capital Rec. None Perf Def: Uneven Bearing <i>SE bearing has lost approximately 50% of bearing due to disintegration of the old south abutment. Debris & vegetation cover east bearings.</i>
Water Channel (1) Channel	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None Perf Def: Lacking Freeboard <i>Open channel, debris on floor members indicate water levels can be high at this location.</i>
Embankment (2) Embankment	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Thick vegetation at bridge wing walls.</i>



Component Inspection Information

Load Posting (4)

Defects **0.0%**

Signs

Damage **0.0%**

Length:

Maintenance **None**

Width:

Capital Rec. **None**

Height:

Bridge posted with 10 tonne limit. Signs located at end of south guide rail. Road is dead end so no signs on north side.

Delineator (4)

Defects **70.0%** **Moderate Obstructed**

Signs

Damage **0.0%**

Length:

Maintenance **None**

Width:

Capital Rec. **None**

Perf Def: Obscured

Height:

Four delineators at ends of guide rail. Signs at north end & at SW are engulfed with vegetation.



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	X	m ²	0.0	\$500	\$0
<i>Deck Concrete Overlay</i>	X	m ²	67.0	\$350	\$0
<i>Deck Replacement</i>	X	m ²	67.0	\$2,000	\$0
<i>Barrier Wall Replacement</i>	X	m	37.4	\$1,500	\$0
<i>Expansion Joint</i>	X	m	10.0	\$3,000	\$0
<i>Waterproof & Pave</i>	X	m ²	67.0	\$200	\$0
<i>Bearing Replacement</i>	X	Count	0.0	\$5,000	\$0
<i>Approach Guide Rail</i>	X	m	80.0	\$200	\$0

Other Work

Abut Repairs

\$10,000

Structural Items Subtotal \$10,000

Mobilization General Sitework 10% \$10,000

Estimated Traffic Management & Civil Items \$0

Contract Admin & Contingencies 20% \$4,000

Total Rehabilitation Cost Estimate \$24,000

Recommended Capital Work Summary

Recommended Capital Year

2019

Abut Repairs

Inspection Comments

Construction year was estimated at 1950. This bridge is unsafe due to the loss of support under the south bearings. Bridge bearing in SE corner is of major concern, loss of concrete in SE corner has left bearing unstable, SW similar but not as bad. Condition of bridge was brought to owners attention, immediate repairs are needed.



Image 42



East elevation

Image 35



South approach

Image 36



North approach

Image 37



NE guide rail

Image 38



East side truss panel

Image 39



Exposed concrete deck



Image 40



East channel

Image 41



West channel

Image 44



SE bearing

Image 45



SE bearing loss support

Image 46



South abutment wall

Image 48



Soffit south end



Image 49



North abutment wall

Image 50



Damaged bottom chord east side

Image 51



Damaged bottom chord west side

Image 52



SW bearing

Image 53



Soffit at north end

Image 54



North abutment wall





Bridge Inspection Report

Johnson Bridge

Road Name: *Morgan Road*
Site ID: *31-A21*
Structure Type: *Precast 3 Sided RF*
Owner: *Township South Stormont*
Built: *2007*
Length: *11.6 m*
Width: *8.5 m*
Spans: *1*
Span Arrange: *10.7*
Feature Under: *Water*
Crossing: *Hoople Creek*
Location: *2 km North of Dafoe Road*

Inspection Date: *August-21-19*
Inspector: *Steve Reid, C.E.T.*
Assistant: *Seamus Fisher, Eng Student*

Comments:
Nice small bridge in good condition. Deck is polished and has wide longitudinal cracks, no delaminations at this time. Waterproof and paving in the near future should be considered.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
WP&P

Estimated Replacement Value: *\$485,000*
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: *88 Years*
Rehabilitation Year and Estimated Cost: *2022 \$66,000*



AADT: *N/A* **Latitude:** *45.01670300*
Lanes: *2* **Longitude:** *-75.01049200*
Skew: *0 °* **Orientation:** *N-S*
Speed: *50 km/h* **Road Width:** *6 m*
Trucks **Load Posting:** *No Posting*



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

RC Topping Slab (1) Deck Surface Length: 11.58 m Width: 8.5 m Height:	Defects 50.0% Moderate Polished Damage 1.0% Moderate Cracking Maintenance None Capital Rec. None <i>Longitudinal cracks notable. Deck surface polished. Chain drag did not find delaminations.</i>
Soffit (1) Deck Soffit Length: 11.58 m Width: 8.5 m Height:	Defects 1.0% Minor Leaching/Seepage Damage 0.0% Maintenance None Capital Rec. None <i>Overall good condition. East & west precast sections are leaking at precast joints. Wet areas on fascia.</i>
Asphalt Wear Surf (1) Apr Wear Surface Length: 6 m Width: 8.5 m Height:	Defects 0.0% Damage 1.0% Minor Potholing Maintenance None Capital Rec. None <i>Minor potholes in south approach.</i>
RC Parapet (2) Barrier Length: 25.71 m Width: 0.4 m Height: 0.9 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>New parapet has the old railing system attached to exterior, assumed for aesthetics. Condition of new parapet is good.</i>
Steel Beam on Steel Post (4) Guide Rail Length: 17.75 m Width: Height:	Defects 0.0% Damage 0.1% Minor Impact Maintenance None Capital Rec. None <i>Guide rail connection at SW corner has minor impact damage at the connection to bridge. Eccentric loader end treatment at all ends of guide rail.</i>
RC Abutment Wall (2) Abutment Stem Length: Width: 9.31 m Height: 2.8 m	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Good condition.</i>



Component Inspection Information

RC Wing Walls (4) Defects **0.0%**
Wing Walls Damage **0.0%**
Length: **7 m** Maintenance **None**
Width: Capital Rec. **None**
Height: **1.67 m** *Good condition.*

Spread Footing (2) Defects **0.0%**
Abutment Foundation Damage **0.0%**
Length: **1 m** Maintenance **None**
Width: **9.4 m** Capital Rec. **None**
Height: **1.2 m** *Good condition. Some rock protection against footings.*

Water Channel (1) Defects **0.0%**
Channel Damage **0.0%**
Maintenance **None**
Capital Rec. **None**
No concerns.

Embankment (4) Defects **0.0%**
Embankment Damage **0.0%**
Maintenance **None**
Capital Rec. **None**
Good condition.



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	X	m ²	0.0	\$500	\$0
<i>Deck Concrete Overlay</i>	X	m ²	98.6	\$350	\$0
<i>Deck Replacement</i>	X	m ²	98.6	\$2,000	\$0
<i>Barrier Wall Replacement</i>	X	m	35.6	\$1,500	\$0
<i>Expansion Joint</i>	X	m	17.0	\$3,000	\$0
<i>Waterproof & Pave</i>	✓	m ²	98.6	\$200	\$19,720
<i>Bearing Replacement</i>	X	Count	0.0	\$5,000	\$0
<i>Approach Guide Rail</i>	X	m	80.0	\$200	\$0

Other Work

\$0

Structural Items Subtotal	\$20,000
Mobilization General Sitework 10%	\$10,000
Estimated Traffic Management & Civil Items	\$25,000
Contract Admin & Contingencies 20%	\$11,000
Total Rehabilitation Cost Estimate	<i>\$66,000</i>

Recommended Capital Work Summary

Recommended Capital Year

2022

WP&P

Inspection Comments

Nice small bridge in good condition. Deck is polished and has wide longitudinal cracks, no delaminations at this time. Waterproof and paving in the near future should be considered.



Image 99



West elevation

Image 92



South approach

Image 93



NE guide rail

Image 94



North approach

Image 95



West barrier wall

Image 96



Exposed concrete deck



Image 97



West channel

Image 98



East channel

Image 100



South abutment wall

Image 101



North abutment wall

Image 102



Soffit (typical)

Image 103



East elevation



Culvert Inspection Report

North Lunenburg Road Culvert

Road Name: North Lunenburg Road, West
Site ID: C31-167
Structure Type: Soil-Steel Structure
Owner: Township South Stormont
Built: 1978
Length: 16.5 m
Width: 3.7 m
Spans: 1
Span Arrange: 3.7
Feature Through: Water
Crossing: Raisin River
Location: 500m East of County Road 14

Inspection Date: August-01-19
Inspector: Harold Kleywegt, P.Eng.
Assistant: Seamus Fisher, Eng Student

Comments:
Culvert is severely perforated and starting to fail. Should be replaced on an urgent basis.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
New Conc Culvert

Estimated Replacement Value: \$278,000
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: 1 Years
Year of Replacement and Cost: 2020 \$327,000



ADT: N/A **Latitude:** 45.05002900
Lanes: 2 **Longitude:** -75.02128600
Skew: 0 ° **Orientation:** E-W
Speed: 80 km/h **Road Width:** 6 m
Trucks: **Load Posting:** No Posting
Fill: 0.5 m **H2O Depth:** 0.3 m



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

Circular CS Plate Pipe (1)	Defects 10.0% Moderate Corrosion	
Conduit	Damage 10.0% Critical Perforation, Major Section Loss	
Length: 16.5 m	Maintenance None	
Width: 3.7 m	Capital Rec. Replace in 1 year	Perf Def: Settlement
Height: 3.7 m	<i>Bottom of culvert has severe perforations along most of its length.</i>	
Asphalt Wear Surf (1)	Defects 0.0%	
Wear Surface	Damage 0.0%	
Length: 3.7 m	Maintenance None	
Width: 6 m	Capital Rec. None	
Height:	<i>Two transverse cracks along sides of culvert suggest road settlement from failing culvert.</i>	
Water Channel (1)	Defects 0.0%	
Outlet Channel	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Part of agricultural drain with uniform bottom width of about 3.5 to 4 m and 1.5:1 side slopes.</i>	
Water Channel (1)	Defects 0.0%	
Conduit Channel	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Clear.</i>	
Water Channel (1)	Defects 0.0%	
Inlet Channel	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Part of agricultural drain with uniform bottom width of about 3.5 to 4 m and 1.5:1 side slopes.</i>	
Embankment (4)	Defects 0.0%	
Embankment	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Well treed and vegetated.</i>	



Capital Needs Cost Estimate Break-Down

<i>Cost of asphalt removal:</i>	\$4,700	<i>Cost of waterproofing:</i>	\$15,300
<i>Cost of dewatering:</i>	\$26,000	<i>Cost of road replace:</i>	\$39,000
<i>Cost erosion control:</i>	\$5,000	<i>Cost of SBGR:</i>	\$21,000
<i>Cost of excavation:</i>	\$32,000	<i>Cost for seeding:</i>	\$500
<i>Cost of existing structure removal:</i>	\$2,000		
<i>Installation Cost for Similar Size Concrete:</i>	\$98,000		

New Concrete Culvert



Structural Items Subtotal	\$258,000
Mobilization General Sitework 10%	\$15,000
Estimated Traffic Management & Civil Items	\$14,000
Contract Admin & Contingencies 20%	\$55,000
Total Rehabilitation Cost Estimate	<i>\$327,000</i>

Recommended Capital Work Summary

Recommended Capital Year **2020**

New Conc Culvert

Inspection Comments

Culvert is severely perforated and starting to fail. Should be replaced on an urgent basis.



Image 64



North elevation

Image 59



West approach

Image 60



East approach

Image 61



Asphalt on deck

Image 62



South channel


Image 63



North channel




Image 65



East wall perforation

Image 66



East wall perforation

Image 67



East wall

Image 68



West wall

Image 69



Culvert invert

Image 70



West wall perforation



Image 71



East wall perforation

Image 72



West wall perforation south inlet

Image 73



South channel

Image 74



100m Downstream



Culvert Inspection Report

North Lunenburg Road Culvert

Road Name: North Lunenburg Road, West
Site ID: C31-169
Structure Type: Soil-Steel Structure
Owner: Township South Stormont
Built: 1974
Length: 21.9 m
Width: 5.8 m
Spans: 1
Span Arrange: 1 @ 5.8
Feature Through: Water
Crossing: Raisin River
Location: 1.2km West of County Road 12

Inspection Date: August-01-19
Inspector: Harold Kleywegt, P.Eng.
Assistant: Seamus Fisher, Eng Student
Comments:
Culvert is in reasonable serviceable condition with possibly 5 to 10 years of remaining service life. Culvert over-sized.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
New Conc Culvert

Estimated Replacement Value: \$357,000
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: 5 Years
Year of Replacement and Cost: 2024 \$446,000



AADT: N/A **Latitude:** 45.06463600
Lanes: 2 **Longitude:** -74.98129800
Skew: 0 ° **Orientation:** N-S
Speed: 80 km/h **Road Width:** 6.7 m
Trucks: **Load Posting:** No Posting
Fill: 0.3 m **H2O Depth:** 0.5 m



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

<p>CS Plate Pipe Arch (1) Conduit</p> <p>Length: 21.9 m Width: 5.8 m Height: 3.7 m</p>	<p>Defects 40.0% Moderate Corrosion</p> <p>Damage 5.0% Moderate Section Loss, Minor Deformation/Bulging</p> <p>Maintenance None Capital Rec. None</p> <p><i>Corroded with full loss of galvanizing in bottom .8 m of culvert. Upper part of culvert in generally good condition, with good shape. Settlement of about 0.3 m from middle to ends. Invert slightly low compared to downstream channel. Bolt line cracking in obvert reported by others.</i></p>
<p>Gravel Surface (1) Wear Surface</p> <p>Length: 4 m Width: 6.7 m Height:</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None Capital Rec. None</p> <p><i>Well graded. Shallow cover over culvert.</i></p>
<p>Water Channel (1) Outlet Channel</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None Capital Rec. None</p> <p><i>Appears to be part of agricultural drain, with uniform cross section of 4 m bottom width and 1.5:1 side slopes.</i></p>
<p>Water Channel (1) Conduit Channel</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None Capital Rec. None</p> <p><i>Power boat moored inside culvert and resting on bottom.</i></p>
<p>Water Channel (1) Inlet Channel</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None Capital Rec. None</p> <p><i>Good alignment.</i></p>
<p>Embankment (1) Embankment</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None Capital Rec. None</p> <p><i>Significant tree growth. Stable slopes.</i></p>



Capital Needs Cost Estimate Break-Down

<i>Cost of asphalt removal:</i>	\$0	<i>Cost of waterproofing:</i>	\$31,800
<i>Cost of dewatering:</i>	\$69,000	<i>Cost of road replace:</i>	\$14,400
<i>Cost erosion control:</i>	\$5,000	<i>Cost of SBGR:</i>	\$21,000
<i>Cost of excavation:</i>	\$32,000	<i>Cost for seeding:</i>	\$500
<i>Cost of existing structure removal:</i>	\$3,000		
<i>Installation Cost for Similar Size Concrete:</i>	\$166,000		

New Concrete Culvert



Structural Items Subtotal	\$357,000
Mobilization General Sitework 10%	\$15,000
Estimated Traffic Management & Civil Items	\$14,000
Contract Admin & Contingencies 20%	\$75,000
Total Rehabilitation Cost Estimate	\$446,000

Recommended Capital Work Summary

Recommended Capital Year **2024**

New Conc Culvert

Inspection Comments

Culvert is in reasonable serviceable condition with possibly 5 to 10 years of remaining service life. Culvert over-sized.



Image 48



West elevation

Image 44



North approach

Image 45



South approach

Image 46



West channel

Image 47



Deck surface

Image 49



West inlet boat



Image 50



North wall bulge

Image 51



North wall

Image 52



South wall

Image 53



Culvert obvert

Image 54



South wall bulge

Image 55



East channel



Image 56



East elevation

Image 57



50m downstream of structure

Image 58



100m downstream of structure



Culvert Inspection Report

Goldfield Road Culvert

Road Name: Goldfield Road
Site ID: C31-A01
Structure Type: Soil-Steel Structure
Owner: Township South Stormont
Built: 2018
Length: 22.1 m
Width: 3.8 m
Spans: 1
Span Arrange: 3.8
Feature Through: Water
Crossing:
Location: 250m North of Hunter Road

Inspection Date: August-20-19
Inspector: Steve Reid, C.E.T.
Assistant: Seamus Fisher, Eng Student

Comments:
New polymer coated pipe arch culvert. No delineators or guide rail were installed at this site.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
No Capital Works Recommendations

Estimated Replacement Value: **\$250,000**
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: **39 Years**



AADT: N/A **Latitude:** 45.09991400
Lanes: 2 **Longitude:** -75.11402400
Skew: 15 ° **Orientation:** N-S
Speed: 80 km/h **Road Width:** 7 m
Trucks: **Load Posting:** No Posting
Fill: 1.2 m **H2O Depth:** 0.3 m



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

CS Plate Pipe Arch (1)

Defects **0.0%**

Conduit

Damage **0.0%**

Length: **22.1 m**

Maintenance **None**

Width: **3.8 m**

Capital Rec. **None**

Height: **2 m**

New culvert. Culvert has polymer coating. Several areas at east exterior had touch up repairs to coating. Bottom of barrel has river stones installed.

Gravel Surface (1)

Defects **0.0%**

Wear Surface

Damage **0.0%**

Length: **3.7 m**

Maintenance **None**

Width: **6.2 m**

Capital Rec. **None**

Height:

New gravel surface.

Small Culv Ret Wall (4)

Defects **0.0%**

Inlet/Outlet Walls

Damage **0.0%**

Length: **1.5 m**

Maintenance **None**

Width:

Capital Rec. **None**

Height: **0.8 m**

Small sheet pile type retaining walls at culvert ends.

Water Channel (1)

Defects **0.0%**

Conduit Channel

Damage **0.0%**

Maintenance **None**

Capital Rec. **None**

No flow at time of inspection 2019. River stones installed through barrel.

Embankment (4)

Defects **0.0%**

Embankment

Damage **0.0%**

Maintenance **None**

Capital Rec. **None**

Rip rap stones on embankments. Ditch culvert in the NW quadrant.



Image 114



East elevation

Image 110



North approach

Image 111



South approach

Image 112



Gravel over culvert

Image 113



East channel

Image 115



South wall



Image 116



North wall

Image 117



Culvert obvert

Image 118



West channel

Image 119



West elevation



Culvert Inspection Report

Hunters Road Culvert

Road Name: *Hunters Road*
Site ID: *C31-A02*
Structure Type: *Soil-Steel Structure*
Owner: *Township South Stormont*
Built: *1976*
Length: *21.8 m*
Width: *3.8 m*
Spans: *1*
Span Arrange: *3.8*
Feature Through *Water*
Crossing:
Location: *60m West of Goldfield Rd South*

Inspection Date: *August-20-19*
Inspector: *Steve Reid, C.E.T.*
Assistant: *Seamus Fisher, Eng Student*

Comments:

Date of construction is likely 1990's not 1976. This culvert has an obvious crimp line along lower barrel walls, walls are easily penetrated with pick hammer in this area. Programming for replacement of this culvert should be started. Plan on replacing this culvert within two years.

Recommended Investigations:

No Special Investigations Recommended


Recommended Capital Works:

New Conc Culvert

Estimated Replacement Value: *\$274,000*
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: *2 Years*
Year of Replacement and Cost: *2021 \$316,000*



AADT: *N/A* **Latitude:** *45.09765100*
Lanes: *2* **Longitude:** *-75.11300400*
Skew: *0 °* **Orientation:** *E-W*
Speed: *80 km/h* **Road Width:** *6.2 m*
Trucks **Load Posting:** *No Posting*
Fill: *0.8 m* **H2O Depth:** *0.3 m*



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

CS Plate Pipe Arch (1) Conduit	Defects 20.0% Minor Corrosion, Moderate Corrosion, Major Corrosion Damage 10.0% Major Crimping, Moderate Perforation
Length: 21.8 m Width: 3.8 m Height: 2.29 m	Maintenance None Capital Rec. Replace in 10 years Perf Def: Load Carrying Capacity <i>Date of construction is most likely incorrect. This culvert has a crimping line in both walls. Perforations are present or the walls can easily be penetrated with pick hammer along this crimp line.</i>
Asphalt Wear Surf (1) Wear Surface	Defects 0.0% Damage 1.0% Minor Cracking
Length: 3.8 m Width: 6.2 m Height:	Maintenance None Capital Rec. None <i>Some edge cracking along pavement shoulders.</i>
Water Channel (1) Conduit Channel	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Upstream & downstream overgrown with vegetation very little flow in channel at time of inspection.</i>
Embankment (4) Embankment	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None Perf Def: Toxic Weeds <i>Wild parsnip present. Thick vegetation on embankments. No guide rail or delineators at this site.</i>



Capital Needs Cost Estimate Break-Down

<i>Cost of asphalt removal:</i>	\$4,200	<i>Cost of waterproofing:</i>	\$8,300
<i>Cost of dewatering:</i>	\$27,000	<i>Cost of road replace:</i>	\$35,000
<i>Cost erosion control:</i>	\$5,000	<i>Cost of SBGR:</i>	\$21,000
<i>Cost of excavation:</i>	\$26,000	<i>Cost for seeding:</i>	\$300
<i>Cost of existing structure removal:</i>	\$2,000		
<i>Installation Cost for Similar Size Concrete:</i>	\$106,000		

New Concrete Culvert



Structural Items Subtotal	\$249,000
Mobilization General Sitework 10%	\$15,000
Estimated Traffic Management & Civil Items	\$14,000
Contract Admin & Contingencies 20%	\$53,000
Total Rehabilitation Cost Estimate	<i>\$316,000</i>

Recommended Capital Work Summary

Recommended Capital Year **2021**

New Conc Culvert

Inspection Comments

Date of construction is likely 1990's not 1976. This culvert has an obvious crimp line along lower barrel walls, walls are easily penetrated with pick hammer in this area. Programming for replacement of this culvert should be started. Plan on replacing this culvert within two years.



Image 125



South elevation

Image 120



West approach

Image 121



East approach

Image 122



Asphalt over culvert

Image 123



North channel


Image 124



South channel



Image 126



East wall

Image 127



West wall

Image 128



Culvert obvert

Image 129



Crimping with perforations wall

Image 130




West wall defined crimping & perforations

Image 131



North elevation





Culvert Inspection Report

Otto Road Culvert

Road Name: *Otto Road*
Site ID: *C31-A03*
Structure Type: *Soil-Steel Structure*
Owner: *Township South Stormont*
Built: *2013*
Length: *17.2 m*
Width: *3.6 m*
Spans: *1*
Span Arrange: *3.6*
Feature Through: *Water*
Crossing:
Location: *4 km West of County Road 14*

Inspection Date: *August-20-19*
Inspector: *Steve Reid, C.E.T.*
Assistant: *Seamus Fisher, Eng Student*

Comments:
Steel box culvert is performing well.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
No Capital Works Recommendations

Estimated Replacement Value: *\$543,000*
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: *34 Years*



AADT: *N/A* **Latitude:** *45.07514200*
Lanes: *2* **Longitude:** *-75.07406800*
Skew: *0 °* **Orientation:** *E-W*
Speed: *80 km/h* **Road Width:** *6.5 m*
Trucks **Load Posting:** *No Posting*
Fill: *0.8 m* **H2O Depth:** *0.3 m*



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

CS Plate Arch (1)	Defects 0.0%
Conduit	Damage 0.0%
Length: 3.55 m	Maintenance None
Width: 17.2 m	Capital Rec. None
Height: 1.42 m	<i>Steel box culvert polymer coating on concrete footings. Culvert is performing well. Several bolts missing.</i>
Asphalt Wear Surf (1)	Defects 0.0%
Wear Surface	Damage 0.0%
Length: 3.55 m	Maintenance None
Width: 6.5 m	Capital Rec. None
Height:	<i>Good condition.</i>
Steel Beam on Steel Post (4)	Defects 0.0%
Guide Rail	Damage 0.0%
Length: 57.6 m	Maintenance None
Width:	Capital Rec. None
Height:	<i>Extruder end treatment at all four ends of guide rail. 82.7m (SW) + 46.7m (NW) + 75.9m (NE) +25.1m (SE)</i>
Thrie Beam G/R (2)	Defects 0.0%
Barrier	Damage 0.0%
Length: 14 m	Maintenance None
Width:	Capital Rec. None
Height:	<i>Small section of thrie beam attached to timber posts locally over culvert. Good condition.</i>
Rip Rap (4)	Defects 0.0%
Channel Armour	Damage 0.0%
	Maintenance None
	Capital Rec. None
	<i>Rip rap placed at culvert ends.</i>
Water Channel (1)	Defects 0.0%
Conduit Channel	Damage 0.0%
	Maintenance None
	Capital Rec. None
	<i>Channel is overgrown. Stagnant water inside culvert.</i>



Component Inspection Information

Embankment (2)

Defects **0.0%**

Embankment

Damage **0.0%**

Maintenance **None**

Capital Rec. **None**

Wild parsnip.

Delineator (4)

Defects **0.0%**

Signs

Damage **0.0%**

Length:

Maintenance **None**

Width:

Capital Rec. **None**

Height:

Delineators located at ends of guide rail.



Image 138



South elevation

Image 132



West approach

Image 133



East approach

Image 134



NE guide rail on approach

Image 135



North thrie beam over culvert

Image 136



Asphalt over culvert



Image 137




South channel

Image 139



East wall

Image 140



West wall

Image 141



Culvert soffit

Image 142



North channel

Image 143



North elevation





Culvert Inspection Report

Beckstead Road Culvert

Road Name: Beckstead Road
Site ID: C31-A06
Structure Type: Soil-Steel Structure
Owner: Township South Stormont
Built: 1980
Length: 14.7 m
Width: 3.6 m
Spans: 1
Span Arrange: 3.6
Feature Through: Water
Crossing:
Location: 2 km East of County Road 11

Inspection Date: August-20-19
Inspector: Steve Reid, C.E.T.
Assistant: Seamus Fisher, Eng Student

Comments:
Construction year was estimated at 1980. Current condition is satisfactory. Lower half of barrel walls has moderate to severe section loss, culvert has approximately 5 years of remaining service life.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
New Conc Culvert

Estimated Replacement Value: \$219,000
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: 5 Years
Year of Replacement and Cost: 2024 \$256,000



AADT: N/A **Latitude:** 45.04875100
Lanes: 2 **Longitude:** -75.06475000
Skew: 20 ° **Orientation:** E-W
Speed: 80 km/h **Road Width:** 6 m
Trucks: **Load Posting:** No Posting
Fill: 0.4 m **H2O Depth:** 0.3 m



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

<p>CS Plate Pipe Arch (1) Conduit</p> <p>Length: 14.7 m Width: 3.6 m Height: 2.29 m</p>	<p>Defects 60.0% Minor Corrosion, Moderate Corrosion, Major Corrosion</p> <p>Damage 3.0% Minor Section Loss</p> <p>Maintenance None</p> <p>Capital Rec. None Perf Def: Insufficient Barrel Length</p> <p><i>Overall barrel condition is satisfactory. Walls above bolt line have minor corrosion, below bolt line walls have moderate to major corrosion with some section loss. Length of culvert is inadequate for road platform, also cover over barrel is minimal. Approximately 500mm of silt has built up inside barrel.</i></p>
<p>Asphalt Wear Surf (1) Wear Surface</p> <p>Length: 3.6 m Width: 6 m Height:</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Surface treatment over culvert, condition is good.</i></p>
<p>Water Channel (1) Conduit Channel</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Channel is overgrown with vegetation both upstream & downstream channels.</i></p>
<p>Embankment (4) Embankment</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None Perf Def: Toxic Weeds</p> <p><i>Steep embankments due to culvert being too short. Wild parsnip present.</i></p>
<p>Delineator (2) Signs</p> <p>Length: Width: Height:</p>	<p>Defects 0.0%</p> <p>Damage 0.0%</p> <p>Maintenance None</p> <p>Capital Rec. None</p> <p><i>Sign in the NE & SW.</i></p>



Capital Needs Cost Estimate Break-Down

<i>Cost of asphalt removal:</i>	\$4,000	<i>Cost of waterproofing:</i>	\$13,200
<i>Cost of dewatering:</i>	\$26,000	<i>Cost of road replace:</i>	\$33,200
<i>Cost erosion control:</i>	\$5,000	<i>Cost of SBGR:</i>	\$21,000
<i>Cost of excavation:</i>	\$17,000	<i>Cost for seeding:</i>	\$300
<i>Cost of existing structure removal:</i>	\$1,000		
<i>Installation Cost for Similar Size Concrete:</i>	\$69,000		

New Concrete Culvert



Structural Items Subtotal	\$199,000
Mobilization General Sitework 10%	\$10,000
Estimated Traffic Management & Civil Items	\$14,000
Contract Admin & Contingencies 20%	\$43,000
Total Rehabilitation Cost Estimate	<i>\$256,000</i>

Recommended Capital Work Summary

Recommended Capital Year **2024**

New Conc Culvert

Inspection Comments

Construction year was estimated at 1980. Current condition is satisfactory. Lower half of barrel walls has moderate to severe section loss, culvert has approximately 5 years of remaining service life.



Image 148



North elevation

Image 144



West approach

Image 145



East approach

Image 146



Asphalt over culvert

Image 147



North channel

Image 149



East wall



Image 150



West wall

Image 151



Culvert obvert

Image 152



East wall close up corrosion

Image 153



South channel

Image 154



South elevation





Culvert Inspection Report

Anderson Road Culvert

Road Name: Anderson Road
Site ID: C31-A08
Structure Type: Concrete Culvert
Owner: Township South Stormont
Built: 1960
Length: 12.2 m
Width: 4.2 m
Spans: 1
Span Arrange: 3.7
Feature Through: Water
Crossing:
Location: 2 km East of Aultsville Road

Inspection Date: August-21-19
Inspector: Steve Reid, C.E.T.
Assistant: Seamus Fisher, Eng Student

Comments:

Construction year was estimated at 1960. This concrete culvert is in good condition. Consider adding delineators to identify culvert.

Recommended Investigations:

No Special Investigations Recommended

Recommended Capital Works:

No Capital Works Recommendations

Estimated Replacement Value: \$222,000


Estimated replacement value is based on replacement in kind

Estimated Remaining Service Life: 31 Years



AADT: N/A **Latitude:** 44.97936300
Lanes: 2 **Longitude:** -75.03533900
Skew: 5 ° **Orientation:** E-W
Speed: 80 km/h **Road Width:** 6.2 m
Trucks: **Load Posting:** No Posting
Fill: 0.4 m **H2O Depth:** 0 m

Bridge Condition



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

CIP RF Open Ftg Culv (1)	Defects 2.0%	Minor Scaling
Conduit	Damage 0.0%	
Length: 12.2 m	Maintenance None	
Width: 4.2 m	Capital Rec. None	
Height: 1.5 m	<i>Overall condition is good. Approximately 500mm of cover over culvert. Minor scaling on walls. Minor scaling on soffit, some damp areas at soffit ends. Scour in the SW corner has undermined footing slightly, see image.</i>	

Asphalt Wear Surf (1)	Defects 0.0%	
Wear Surface	Damage 0.0%	
Length: 4.2 m	Maintenance None	
Width: 6.2 m	Capital Rec. None	
Height:	<i>Surface treatment, satisfactory condition.</i>	

Water Channel (1)	Defects 0.0%	
Conduit Channel	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Dry at time of inspection, 2019. Overgrown upstream & downstream.</i>	

Embankment (4)	Defects 0.0%	
Embankment	Damage 0.0%	
	Maintenance Remove Brush/Trees	
	Capital Rec. None	
	<i>Heavy vegetation growth. No guide rail or delineators at this site. Brush & trees at south end should be cleared.</i>	



Image 121



North elevation

Image 117



West approach

Image 118



East approach

Image 119



Wearing surface over culvert

Image 120



North channel

Image 122



East wall



Image 123



West wall

Image 124



Soffit (typical)

Image 125



SW corner footing under cut

Image 126



South elevation

Image 127



South channel



Culvert Inspection Report

Finch-Osnabruck Boundary Rd Culvert

Road Name: *Finch-Osnabruck Boundary Rd*
Site ID: *C31-A10*
Structure Type: *Soil-Steel Structure*
Owner: *Township South Stormont*
Built: *1995*
Length: *12.4 m*
Width: *3.9 m*
Spans: *1*
Span Arrange: *3.9*
Feature Through: *Water*
Crossing:
Location: *30 m North of County Rd 14*

Inspection Date: *August-20-19*
Inspector: *Steve Reid, C.E.T.*
Assistant: *Seamus Fisher, Eng Student*

Comments:
Construction year was estimated at 1995. Inadequate cover may be contributing to cusping. A topping slab is recommended to better distribute wheel loads, alternatively add an additional 0.3 m cover.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
Topping Slab

Estimated Replacement Value: *\$243,000*
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: *11 Years*
Rehabilitation Year and Estimated Cost: *2020 \$72,000*



AADT: *N/A* **Latitude:** *45.13739300*
Lanes: *2* **Longitude:** *-75.02494800*
Skew: *20 °* **Orientation:** *E-W*
Speed: *80 km/h* **Road Width:** *7.3 m*
Trucks: **Load Posting:** *No Posting*
Fill: *0.3 m* **H2O Depth:** *0.5 m*



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

CS Plate Pipe Arch (1)	Defects 50.0%	Minor Corrosion, Moderate Corrosion
Conduit	Damage 5.0%	Minor Section Loss, Moderate Cusping
Length: 12.4 m	Maintenance None	
Width: 3.9 m	Capital Rec. None	
Height: 2.69 m	<i>Generally in good condition. Minor to moderate corrosion over lower half of barrel. Bevelled ends.</i>	
Asphalt Wear Surf (1)	Defects 0.0%	
Wear Surface	Damage 2.0%	Minor Cracking
Length: 3.9 m	Maintenance None	
Width: 7.3 m	Capital Rec. None	
Height:	<i>Several random cracks.</i>	
Steel Beam on Wood Post (Defects 0.0%	
Guide Rail	Damage 1.0%	Minor Impact
Length: 24 m	Maintenance None	
Width:	Capital Rec. None	
Height: 0.72 m	<i>Eccentric loader end treatment in the NW corner. Guide rail is satisfactory at this time. 29m (W), 19m (E)</i>	
Water Channel (1)	Defects 2.0%	Minor Aggradation
Conduit Channel	Damage 2.0%	Minor Debris Obstruction
	Maintenance Remove Obstructions	
	Capital Rec. None	
	<i>West end of culvert partially blocked by fallen trees. Aggradation against the north wall inside barrel. Stagnant water inside barrel.</i>	
Embankment (4)	Defects 0.0%	
Embankment	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Satisfactory condition.</i>	



Capital Needs Cost Estimate Break-Down

Other Work
Topping Slab

\$50,000

Structural Items Subtotal **\$50,000**

Mobilization General Sitework 10% **\$10,000**

Estimated Traffic Management & Civil Items **\$0**

Contract Admin & Contingencies 20% **\$12,000**

Total Rehabilitation Cost Estimate ***\$72,000***

Recommended Capital Work Summary

Recommended Capital Year

2020

Topping Slab

Inspection Comments

Construction year was estimated at 1995. Inadequate cover may be contributing to cusping. A topping slab is recommended to better distribute wheel loads, alternatively add an additional 0.3 m cover.



Image 103



East elevation

Image 97



North approach

Image 98



South approach

Image 99



West guide rail

Image 100



Asphalt over culvert with flexural cracking

Image 101



East channel



Image 104




North wall

Image 105



South wall

Image 106



Culvert obvert with obvious cusping

Image 107



West channel

Image 108



West elevation

Image 109



West inlet debris





Culvert Inspection Report

Cooper Road Culvert

Road Name: Cooper Road
Site ID: C31-A12
Structure Type: Concrete Culvert
Owner: Township South Stormont
Built: 1994
Length: 21.7 m
Width: 4.8 m
Spans: 1
Span Arrange: 4.8
Feature Through: Water
Crossing:
Location: 2 km West of County Road 12

Inspection Date: August-21-19
Inspector: Steve Reid, C.E.T.
Assistant: Seamus Fisher, Eng Student

Comments:
This culvert is in good condition. Guide rail over culvert is due for replacement.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
Guide Rail

Estimated Replacement Value: \$334,000
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: 65 Years
Rehabilitation Year and Estimated Cost: 2021 \$36,000



AADT: N/A **Latitude:** 45.08249500
Lanes: 2 **Longitude:** -75.00437100
Skew: 0 ° **Orientation:** E-W
Speed: 80 km/h **Road Width:** 6 m
Trucks: **Load Posting:** No Posting
Fill: 0.5 m **H2O Depth:** 0.3 m



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

Precast RF Box Culvert (1)	Defects 5.0%	Minor Scaling, Minor Staining
Conduit	Damage 0.0%	
Length: 21.7 m	Maintenance None	
Width: 4.2 m	Capital Rec. None	
Height: 1.8 m	<i>Condition of interior is good. Walls are lightly scaled. Minor stains around precast joints in soffit.</i>	
Asphalt Wear Surf (1)	Defects 0.0%	
Wear Surface	Damage 0.0%	
Length: 4.7 m	Maintenance None	
Width: 6 m	Capital Rec. None	
Height:	<i>Asphalt on approaches is in poor condition, asphalt over culvert is satisfactory.</i>	
Steel Beam on Wood Post (Defects 0.0%	
Guide Rail	Damage 5.0%	Major Decay
Length: 20 m	Maintenance None	
Width:	Capital Rec. Replace in 2 years	Perf Def: Inadequate Height
Height: 0.5 m	<i>Guide rail is too low to be an effective traffic barrier. Timber posts have major decay in top surface. Major vegetation growth around guide rail.</i>	
Water Channel (1)	Defects 5.0%	Minor Aggradation
Conduit Channel	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Little flow at time of inspection. Aggradation noted at SE end & along east wall inside barrel.</i>	
Embankment (4)	Defects 0.0%	
Embankment	Damage 0.0%	
	Maintenance Remove Brush/Trees	
	Capital Rec. None	Perf Def: Toxic Weeds
	<i>Thick vegetation at culvert ends. Wild parsnip present. Tree in the SE corner should be cut back.</i>	



Image 11



South elevation

Image 1



East approach

Image 2



West approach

Image 3



South guide rail

Image 4



Asphalt over culvert

Image 5



North channel



Image 6



North elevation

Image 7



West wall

Image 8



East wall

Image 9



Soffit (typical)

Image 10



South channel





Culvert Inspection Report

Wilburn Road Culvert

Road Name: Wilburn Road
Site ID: C31-A13
Structure Type: Soil-Steel Structure
Owner: Township South Stormont
Built: 1990
Length: 11.2 m
Width: 3.5 m
Spans: 1
Span Arrange: 3.5
Feature Through: Water
Crossing:
Location: 0.5 km West of County Road 12

Inspection Date: August-21-19
Inspector: Steve Reid, C.E.T.
Assistant: Seamus Fisher, Eng Student

Comments:

Construction Year was estimated at 1990. Culvert is in satisfactory condition at this time. Major corrosion and bolt line cracks were identified, planning for replacement of this culvert in a 10-15 year timeframe should be started.

Recommended Investigations:

No Special Investigations Recommended

Recommended Capital Works:

No Capital Works Recommendations


Estimated Replacement Value: \$146,000

Estimated replacement value is based on replacement in kind

Estimated Remaining Service Life: 11 Years



AADT: N/A **Latitude:** 45.08254500
Lanes: 1 **Longitude:** -74.98669300
Skew: 0 ° **Orientation:** E-W
Speed: 80 km/h **Road Width:** 4 m
Trucks: **Load Posting:** No Posting
Fill: 1.2 m **H2O Depth:** 0.2 m



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

CS Plate Pipe Arch (1) Conduit	Defects 60.0% Minor Corrosion, Moderate Corrosion, Major Corrosion Damage 2.0% Minor Section Loss, Minor Bolt Line Crack'g
Length: 11.2 m Width: 3.5 m Height: 2 m	Maintenance None Capital Rec. None Perf Def: Insufficient Barrel Length <i>Barrel walls have light corrosion above bolt line seam, below seam corrosion is moderate to major with minor section loss. Bolt line cracks were noted in the west wall, (approximately 2m length). Minor impact type damage at south end. Culvert length is insufficient for road platform.</i>
Gravel Surface (1) Wear Surface	Defects 0.0% Damage 0.0%
Length: 3.5 m Width: 4 m Height:	Maintenance None Capital Rec. None <i>Narrow gravel road, dead end. Loose gravel.</i>
Water Channel (1) Conduit Channel	Defects 0.0% Damage 1.0% Minor Debris Obstruction Maintenance Remove Obstructions Capital Rec. None Perf Def: Obstructed <i>Stagnant flow. Large downed tree limb inside barrel.</i>
Embankment (4) Embankment	Defects 0.0% Damage 0.0% Maintenance Remove Brush/Trees Capital Rec. None Perf Def: Toxic Weeds <i>Steep embankments. Wild parsnip present.</i>



Image 16



South elevation

Image 12



East approach

Image 13



West approach

Image 14



Gravel surface over culvert

Image 15



South channel

Image 17



West wall



Image 18



East wall

Image 19



Barrel obvert

Image 20



Bolt line cracks west wall

Image 21



North channel

Image 22



North elevation



Culvert Inspection Report

MacRae Road Culvert

Road Name: *MacRae Road*
Site ID: *C31-A15*
Structure Type: *Soil-Steel Structure*
Owner: *Township South Stormont*
Built: *1985*
Length: *18.2 m*
Width: *3.3 m*
Spans: *1*
Span Arrange: *3.3*
Feature Through *Water*
Crossing:
Location: *1.5km north of Dixon Road*

Inspection Date: *August-20-19*
Inspector: *Steve Reid, C.E.T.*
Assistant: *Seamus Fisher, Eng Student*

Comments:
Construction year was estimated at 1995. Perforations were noted in barrel wall and floor. A concrete floor liner may be an appropriate repair strategy for this culvert due to the perforations being low in floor or walls. Without liner this culvert will need replacement in 5 - 10 year timeframe. Floor liner would add 20 years to life of culvert.


Recommended Investigations:
No Special Investigations Recommended

Recommended Capital Works:
Concrete floor liner

Estimated Replacement Value: *\$213,000*
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: *6 Years*
Rehabilitation Year and Estimated Cost: *2023 \$36,000*



AADT: *N/A* **Latitude:** *45.10873800*
Lanes: *2* **Longitude:** *-74.96583200*
Skew: *0 °* **Orientation:** *N-S*
Speed: *80 km/h* **Road Width:** *5.5 m*
Trucks **Load Posting:** *No Posting*
Fill: *0.8 m* **H2O Depth:** *0.4 m*



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

<p>Circular CS Pipe (1) Conduit Length: 18.2 m Width: 3.3 m Height: 2.3 m</p>	<p>Defects 30.0% Minor Corrosion, Moderate Corrosion Damage 2.0% Minor Perforation Maintenance None Capital Rec. Replace in 5 years</p> <p><i>Lower third of barrel has moderate corrosion. Perforations at normal waterline at the east end. Random perforations along seams of barrel.</i></p>
<p>Gravel Surface (1) Wear Surface Length: 3.3 m Width: 5.5 m Height:</p>	<p>Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None</p> <p><i>Gravel road over culvert.</i></p>
<p>Water Channel (1) Conduit Channel</p>	<p>Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None</p> <p><i>Channel is open & moving through culvert. Remains of old bridge abutments west of culvert.</i></p>
<p>Embankment (2) Embankment</p>	<p>Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None</p> <p>Perf Def: Over-steepened</p> <p><i>No guide rail or delineators at this site. Steep embankments.</i></p>



Capital Needs Cost Estimate Break-Down

Other Work

Concrete floor liner

\$20,000

Structural Items Subtotal \$20,000

Mobilization General Sitework 10% \$10,000

Estimated Traffic Management & Civil Items \$0

Contract Admin & Contingencies 20% \$6,000

Total Rehabilitation Cost Estimate *\$36,000*

Recommended Capital Work Summary

Recommended Capital Year

2023

Concrete floor liner

Inspection Comments

Construction year was estimated at 1995. Perforations were noted in barrel wall and floor. A concrete floor liner may be an appropriate repair strategy for this culvert due to the perforations being low in floor or walls. Without liner this culvert will need replacement in 5 - 10 year timeframe. Floor liner would add 20 years to life of culvert.



Image 89



West elevation

Image 84



North approach

Image 85



South approach

Image 87



East channel

Image 88



West channel

Image 90



North wall



Image 91



South wall

Image 92



Culvert obvert

Image 93



Through barrel from west

Image 94



North wall mid length wall perforations

Image 95



East channel

Image 96



East elevation





Culvert Inspection Report

Northfield Road Culvert

Road Name: Northfield Road
Site ID: C31-A16
Structure Type: Soil-Steel Structure
Owner: Township South Stormont
Built: 1990
Length: 15.3 m
Width: 3.6 m
Spans: 1
Span Arrange: 3.6
Feature Through: Water
Crossing:
Location: 1 km North of County Road 18

Inspection Date: August-20-19
Inspector: Steve Reid, C.E.T.
Assistant: Seamus Fisher, Eng Student

Comments:

*Construction year was estimated at 1990.
 Delineators should be installed to identify culvert.
 Current condition of this steel pipe arch culvert is satisfactory.*

Recommended Investigations:

No Special Investigations Recommended

Recommended Capital Works:

No Capital Works Recommendations


Estimated Replacement Value: \$194,000

Estimated replacement value is based on replacement in kind

Estimated Remaining Service Life: 16 Years



AADT: N/A **Latitude:** 45.07444300
Lanes: 2 **Longitude:** -74.93634500
Skew: 0 ° **Orientation:** N-S
Speed: 80 km/h **Road Width:** 7.5 m
Trucks: **Load Posting:** No Posting
Fill: 0.6 m **H2O Depth:** 0.3 m



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

CS Plate Pipe Arch (1)	Defects 40.0% Minor Corrosion, Moderate Corrosion, Moderate Plate Lapping Reversed
Conduit	Damage 5.0% Minor Section Loss, Moderate Cusping
Length: 15.3 m	Maintenance None
Width: 3.6 m	Capital Rec. None
Height: 2.29 m	<i>Light corrosion at high water line & below. Moderate corrosion with minor section loss at normal water line. Obvert of culvert has reverse curvature (cusping), and incorrect plate lapping.</i>
Gravel Surface (1)	Defects 0.0%
Wear Surface	Damage 0.0%
Length: 3.6 m	Maintenance None
Width: 7.5 m	Capital Rec. None
Height:	<i>Gravel road over culvert.</i>
Water Channel (1)	Defects 0.0%
Conduit Channel	Damage 0.0%
	Maintenance None
	Capital Rec. None
	<i>Stagnant water at time of inspection. High water level appears to be half way up the barrel wall.</i>
Embankment (4)	Defects 0.0%
Embankment	Damage 0.0%
	Maintenance None
	Capital Rec. None
	<i>No guide rail or delineators at this site. Thick vegetation at culvert ends. Dry stone retaining walls at culvert ends hard to see due to thick vegetation.</i>



Image 83



East elevation

Image 73



North approach

Image 74



South approach

Image 75



Gravel over culvert

Image 76



West channel

Image 77



East channel




Image 78




West elevation

Image 79



North wall

Image 80



South wall

Image 81



Culvert obvert

Image 82



Through barrel from west



Culvert Inspection Report

O'Keefe Road Culvert

Road Name: O'Keefe Road
Site ID: C31-A18
Structure Type: Soil-Steel Structure
Owner: Township South Stormont
Built: 1975
Length: 17.2 m
Width: 3.2 m
Spans: 1
Span Arrange: 3.2
Feature Through: Water
Crossing:
Location: 1km South of Myers Road

Inspection Date: August-20-19
Inspector: Steve Reid, C.E.T.
Assistant: Seamus Fisher, Eng Student

Comments:

Age of this culvert should be verified, more likely constructed in 90's not 1975. Culvert is in satisfactory condition at this time. Guide rail protection should be updated within 2 years.

Recommended Investigations:

No Special Investigations Recommended


Recommended Capital Works:

Guide rail

Estimated Replacement Value: \$250,000
Estimated replacement value is based on replacement in kind
Estimated Remaining Service Life: 11 Years
Rehabilitation Year and Estimated Cost: 2020 \$48,000



AADT: N/A **Latitude:** 45.11210600
Lanes: 2 **Longitude:** -74.83444100
Skew: 20 ° **Orientation:** N-S
Speed: 80 km/h **Road Width:** 5.5 m
Trucks: **Load Posting:** No Posting
Fill: 1.2 m **H2O Depth:** 0.5 m



BCI = Bridge Condition Index MTO Calculation

PD = Parabolic Depreciation
% retained value

SLD = Straight Line Depreciation
% retained value

DD = Defects and Damage
% loss of retained value



Component Inspection Information

Circular CS Pipe (1) Conduit Length: 17.2 m Width: 3.2 m Height: 2.1 m	Defects 40.0% Moderate Corrosion, Major Corrosion Damage 2.0% Minor Section Loss Maintenance None Capital Rec. None <i>Date of construction should be verified, unlikely this culvert was constructed in 1975. Bottom third of culvert has moderate to major corrosion with some minor section loss.</i>
Asphalt Wear Surf (1) Wear Surface Length: 3.2 m Width: 5.5 m Height:	Defects 1.0% Minor Ravelling Damage 0.0% Maintenance None Capital Rec. None <i>Minor ravelling.</i>
Steel Beam on Wood Post (Guide Rail Length: 30.5 m Width: Height: 0.8 m	Defects 0.0% Damage 5.0% Major Decay Maintenance None Capital Rec. Replace in 2 years <i>Many posts have major decay. Ends are not properly buried. Sections of flex beam badly corroded. Guide rail system requires renewal.</i>
Water Channel (1) Conduit Channel	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Stagnant flow, no water in upstream or downstream, barrel has 600mm stagnant water inside. Channel bottom stones.</i>
Embankment (4) Embankment	Defects 0.0% Damage 5.0% Moderate Local Instability Maintenance Remove Brush/Trees Capital Rec. None <i>Thick brush. Wild parsnip. Dry stone retaining wall in NW is partially failed.</i>



Capital Needs Cost Estimate Break-Down

Other Work
Guide rail

\$30,000

Structural Items Subtotal **\$30,000**

Mobilization General Sitework 10% **\$10,000**

Estimated Traffic Management & Civil Items **\$0**

Contract Admin & Contingencies 20% **\$8,000**

Total Rehabilitation Cost Estimate ***\$48,000***

Recommended Capital Work Summary

Recommended Capital Year **2020**

Guide rail

Inspection Comments

Age of this culvert should be verified, more likely constructed in 90's not 1975. Culvert is in satisfactory condition at this time. Guide rail protection should be updated within 2 years.



Image 49



West elevation

Image 44



North approach

Image 45



South approach

Image 46



East guide rail

Image 47



Asphalt over culvert

Image 48



West channel



Image 50




North wall

Image 51



South wall

Image 52



Culvert obvert

Image 53



North wall corrosion at water line

Image 54



East channel

Image 55



East elevation



